

### 3 motor single phase industrial vacuum cleaner for hazardous dust

S3 L, M and H models are equipped with 3 bypass motors, they are easy to use with monitored filter performance. L-M-H certified for the collection of hazardous dusts.

S3 L M and H models are equipped with a control panel supplying real-time information about the vacuum efficiency. They are available with 50 or 100 litre containers, L-M-H certified, in stainless steel, with absolute filter HEPA H14 (for the collection of very fine or toxic dust), with nomex filter (ideal in case of collecting of hot substances), with electric filter shaker.





There are many versions to suit varying needs.

- L, M, H certified to safely collect hazardous material
- Monitoring of the vacuum efficiency
- Ergonomic
- High filtering efficiency
- Low noise
- Robust construction for industrial applications





Picture shown may not represent model quoted

● Standard equipment







Included accessories	Ref. no.	Min. required	S3 L100 LC	S3 L100 LC UKP	S3 L100 LC V110 UKP
<b>Hose Vacuum Cleaner</b>					
 AIR HOSE D50MT5+SLEEVES	Z7 22363	1			
<b>Vac Nozzle Dry</b>					
 MOBILE SUCKER D50 MM300 FE COMPLETE	Z7 22172	1			
<b>Cone Nozzle</b>					
 CONIC TUBE D50 RUBBER	Z7 21010	1			
<b>Crevice Nozzle</b>					
 FLAT LANCE D50 ZINC PLT.	Z7 21026	1			
<b>Assembly</b>					
GRID AND VALVE D460 FE COMPLETE	Z5 60034	1			
<b>Vacuum Hose and Connection</b>					



## 3 motor single phase industrial vacuum cleaner for hazardous dust







Included accessories	Ref. no.	Min. required	S3 L100 LC	S3 L100 LC UKP	S3 L100 LC V110 UKP
 REDUCER IRON D70/50	Z7 22001	1			
<b>Extension Tube</b>					
 HANDGRIP D50 ALUMINIUM COMPLETE	Z7 22025	1			

- Standard equipment


Included accessories	Ref. no.	Min. required	S3 L100 LC GV CC UKP	S3 L100 LC GV CC V110 UKP	S3 L50 LC
<b>Hose Vacuum Cleaner</b>					
 AIR HOSE D50MT5+SLEEVES	Z7 22363	1			
<b>Vac Nozzle Dry</b>					
 MOBILE SUCKER D50 MM300 FE COMPLETE	Z7 22172	1			
<b>Cone Nozzle</b>					
 CONIC TUBE D50 RUBBER	Z7 21010	1			
<b>Crevice Nozzle</b>					
 FLAT LANCE D50 ZINC PLT.	Z7 21026	1			
<b>Assembly</b>					
GRID AND VALVE D460 FE COMPLETE	Z5 60034	1	•		
<b>Vacuum Hose and Connection</b>					
 REDUCER IRON D70/50	Z7 22001	1			
<b>Extension Tube</b>					
 HANDGRIP D50 ALUMINIUM COMPLETE	Z7 22025	1			

## 3 motor single phase industrial vacuum cleaner for hazardous dust

## ● Standard equipment






Included accessories	Ref. no.	Min. required	S3 L100 LC FM	S3 L100 LC AU	S3 L100 LC AU UKP
<b>Hose Vacuum Cleaner</b>					
 AIR HOSE D50MT5+SLEEVES	Z7 22363	1			
<b>Vac Nozzle Dry</b>					
 MOBILE SUCKER D50 MM300 FE COMPLETE	Z7 22172	1			
<b>Cone Nozzle</b>					
 CONIC TUBE D50 RUBBER	Z7 21010	1			
<b>Crevice Nozzle</b>					
 FLAT LANCE D50 ZINC PLT.	Z7 21026	1			
<b>Assembly</b>					
GRID AND VALVE D460 FE COMPLETE	Z5 60034	1			
<b>Vacuum Hose and Connection</b>					
 REDUCER IRON D70/50	Z7 22001	1			
<b>Extension Tube</b>					
 HANDGRIP D50 ALUMINIUM COMPLETE	Z7 22025	1			

## ● Standard equipment




Included accessories	Ref. no.	Min. required	S3 L100 LC AU V110 UKP	S3 L50 LC AU	S3 L50 LC V110 UKP
<b>Hose Vacuum Cleaner</b>					
 AIR HOSE D50MT5+SLEEVES	Z7 22363	1			
<b>Vac Nozzle Dry</b>					



## 3 motor single phase industrial vacuum cleaner for hazardous dust




Included accessories	Ref. no.	Min. required	S3 L100 LC AU V110 UKP	S3 L50 LC AU	S3 L50 LC V110 UKP
 MOBILE SUCKER D50 MM300 FE COMPLETE	Z7 22172	1			
<b>Cone Nozzle</b>					
 CONIC TUBE D50 RUBBER	Z7 21010	1			
<b>Crevice Nozzle</b>					
 FLAT LANCE D50 ZINC PLT.	Z7 21026	1			
<b>Assembly</b>					
GRID AND VALVE D460 FE COMPLETE	Z5 60034	1			
<b>Vacuum Hose and Connection</b>					
 REDUCER IRON D70/50	Z7 22001	1			
<b>Extension Tube</b>					
 HANDGRIP D50 ALUMINIUM COMPLETE	Z7 22025	1			

- Standard equipment





Included accessories	Ref. no.	Min. required	S3 L100 LC L GV CC	S3 L100 LC L GV CC UKP	S3 L100 LC L GV CC 2X
<b>Hose Vacuum Cleaner</b>					
 AIR HOSE D50MT5+SLEEVES	Z7 22363	1			
<b>Vac Nozzle Dry</b>					
 MOBILE SUCKER D50 MM300 FE COMPLETE	Z7 22172	1			
<b>Cone Nozzle</b>					
 CONIC TUBE D50 RUBBER	Z7 21010	1			
<b>Crevice Nozzle</b>					



## 3 motor single phase industrial vacuum cleaner for hazardous dust



Included accessories	Ref. no.	Min. required	S3 L100 LC L GV CC	S3 L100 LC L GV CC UKP	S3 L100 LC L GV CC 2X
 FLAT LANCE D50 ZINC PLT.	Z7 21026	1			
<b>Assembly</b>					
GRID AND VALVE D460 FE COMPLETE	Z5 60034	1	•	•	•
<b>Vacuum Hose and Connection</b>					
 REDUCER IRON D70/50	Z7 22001	1			
<b>Extension Tube</b>					
 HANDGRIP D50 ALUMINIUM COMPLETE	Z7 22025	1			

## • Standard equipment







Included accessories	Ref. no.	Min. required	S3 L50 LC GV CC	S3 L50 LC L GV CC 3X	S3 L100 LC FM AU UKP
<b>Hose Vacuum Cleaner</b>					
 AIR HOSE D50MT5+SLEEVES	Z7 22363	1			
<b>Vac Nozzle Dry</b>					
 MOBILE SUCKER D50 MM300 FE COMPLETE	Z7 22172	1			
<b>Cone Nozzle</b>					
 CONIC TUBE D50 RUBBER	Z7 21010	1			
<b>Crevice Nozzle</b>					
 FLAT LANCE D50 ZINC PLT.	Z7 21026	1			
<b>Assembly</b>					
GRID AND VALVE D460 FE COMPLETE	Z5 60034	1	•		
<b>Vacuum Hose and Connection</b>					



3 motor single phase industrial vacuum cleaner for hazardous dust

Included accessories	Ref. no.	Min. required	S3 L50 LC GV CC	S3 L50 LC L GV CC 3X	S3 L100 LC FM AU UKP
 REDUCER IRON D70/50	Z7 22001	1			
<b>Extension Tube</b>					
 HANDGRIP D50 ALUMINIUM COMPLETE	Z7 22025	1			







• Standard equipment

Included accessories	Ref. no.	Min. required	S3 L50 LC FM AU	S3 L50 LC PBS AU UKP	S3 L100 LC L GV CC AU UKP
<b>Hose Vacuum Cleaner</b>					
 AIR HOSE D50MT5+SLEEVES	Z7 22363	1			
<b>Vac Nozzle Dry</b>					
 MOBILE SUCKER D50 MM300 FE COMPLETE	Z7 22172	1			
<b>Cone Nozzle</b>					
 CONIC TUBE D50 RUBBER	Z7 21010	1			
<b>Crevice Nozzle</b>					
 FLAT LANCE D50 ZINC PLT.	Z7 21026	1			
<b>Assembly</b>					
GRID AND VALVE D460 FE COMPLETE	Z5 60034	1			
<b>Vacuum Hose and Connection</b>					
 REDUCER IRON D70/50	Z7 22001	1			
<b>Extension Tube</b>					
 HANDGRIP D50 ALUMINIUM COMPLETE	Z7 22025	1			




3 motor single phase industrial vacuum cleaner for hazardous dust

• Standard equipment






Included accessories	Ref. no.	Min. required	S3 L100 LC L GV CC AU V110 UKP	S3 MC LP UKP	S3 HC LP UKP
<b>Hose Vacuum Cleaner</b>					
 AIR HOSE D50MT5+SLEEVES	Z7 22363	1			
<b>Vac Nozzle Dry</b>					
 MOBILE SUCKER D50 MM300 FE COMPLETE	Z7 22172	1			
<b>Cone Nozzle</b>					
 CONIC TUBE D50 RUBBER	Z7 21010	1			
<b>Crevice Nozzle</b>					
 FLAT LANCE D50 ZINC PLT.	Z7 21026	1			
<b>Assembly</b>					
GRID AND VALVE D460 FE COMPLETE	Z5 60034	1			
<b>Vacuum Hose and Connection</b>					
 REDUCER IRON D70/50	Z7 22001	1			
<b>Extension Tube</b>					
 HANDGRIP D50 ALUMINIUM COMPLETE	Z7 22025	1			

• Standard equipment

Included accessories	Ref. no.	Min. required	S3 HC LP V110 UKP	S3CB L100 LC FM	S3CB L100 LC FM V110 UKP
<b>Hose Vacuum Cleaner</b>					
 AIR HOSE D50MT5+SLEEVES	Z7 22363	1		•	•
<b>Vac Nozzle Dry</b>					



## 3 motor single phase industrial vacuum cleaner for hazardous dust

Included accessories	Ref. no.	Min. required	S3 HC LP V110 UKP	S3CB L100 LC FM	S3CB L100 LC FM V110 UKP
 MOBILE SUCKER D50 MM300 FE COMPLETE	Z7 22172	1		•	•
<b>Cone Nozzle</b>					
 CONIC TUBE D50 RUBBER	Z7 21010	1		•	•
<b>Crevice Nozzle</b>					
 FLAT LANCE D50 ZINC PLT.	Z7 21026	1		•	•
<b>Assembly</b>					
GRID AND VALVE D460 FE COMPLETE	Z5 60034	1			
<b>Vacuum Hose and Connection</b>					
 REDUCER IRON D70/50	Z7 22001	1		•	•
<b>Extension Tube</b>					
 HANDGRIP D50 ALUMINIUM COMPLETE	Z7 22025	1		•	•

Model	S3 L100 LC	S3 L100 LC UKP	S3 L100 LC V110 UKP
Ref. no.	4010300177	4010300178	4010300179

## PRODUCT FEATURES

Manual filter shaker	•	•	•
Electrical filter shaker			
Cyclone system			
Stainless steel container			
M-class hazardous dust approval			
H-class hazardous dust approval			
Uk model		•	•
Power connected indicator	•	•	•
HEPA full indicator (electronic)			
HEPA (H14) upstream filtration			
100 l. bin	•	•	•





## 3 motor single phase industrial vacuum cleaner for hazardous dust

Model	S3 L100 LC	S3 L100 LC UKP	S3 L100 LC V110 UKP
Ref. no.	4010300177	4010300178	4010300179

## PRODUCT FEATURES

Automatic shut-off for liquid

M class filter

50 l. bin

Stainless steel container &amp; filter chamber

L-class hazardous dust approval

Main filter clogged indicator (electronic)

Automatic stopping for solids

Grid and valve

Fully in stainless steel

Plastic bag system

Suitable for liquids

Longopac® system

Model	S3 L100 LC GV CC UKP	S3 L100 LC GV CC V110 UKP	S3 L50 LC
Ref. no.	4010300184	4010300185	4010300190

## PRODUCT FEATURES

Manual filter shaker

Electrical filter shaker

Cyclone system

Stainless steel container

M-class hazardous dust approval

H-class hazardous dust approval

Uk model

Power connected indicator

HEPA full indicator (electronic)

HEPA (H14) upstream filtration

100 l. bin

Automatic shut-off for liquid

M class filter

50 l. bin

Stainless steel container &amp; filter chamber

L-class hazardous dust approval

Main filter clogged indicator (electronic)

Automatic stopping for solids



3 motor single phase industrial vacuum cleaner for hazardous dust

Model	S3 L100 LC GV CC UKP	S3 L100 LC GV CC V110 UKP	S3 L50 LC
Ref. no.	4010300184	4010300185	4010300190

PRODUCT FEATURES

Grid and valve	•	•	
Fully in stainless steel			
Plastic bag system			
Suitable for liquids			
Longopac® system			

Model	S3 L100 LC FM	S3 L100 LC AU	S3 L100 LC AU UKP
Ref. no.	4010300195	4010300204	4010300205

PRODUCT FEATURES

Manual filter shaker	•	•	•
Electrical filter shaker			
Cyclone system			
Stainless steel container			
M-class hazardous dust approval			
H-class hazardous dust approval			
Uk model			•
Power connected indicator	•	•	•
HEPA full indicator (electronic)		•	•
HEPA (H14) upstream filtration		•	•
100 l. bin	•	•	•
Automatic shut-off for liquid			
M class filter	•		
50 l. bin			
Stainless steel container & filter chamber			
L-class hazardous dust approval	•	•	•
Main filter clogged indicator (electronic)	•	•	•
Automatic stopping for solids			
Grid and valve			
Fully in stainless steel			
Plastic bag system			
Suitable for liquids			
Longopac® system			



## 3 motor single phase industrial vacuum cleaner for hazardous dust

Model	S3 L100 LC AU V110 UKP	S3 L50 LC AU	S3 L50 LC V110 UKP
Ref. no.	4010300206	4010300243	4010300245

## PRODUCT FEATURES

Manual filter shaker	•	•	•
Electrical filter shaker			
Cyclone system			
Stainless steel container			
M-class hazardous dust approval			
H-class hazardous dust approval			
Uk model	•		•
Power connected indicator	•	•	•
HEPA full indicator (electronic)	•	•	
HEPA (H14) upstream filtration	•	•	
100 l. bin	•		
Automatic shut-off for liquid			
M class filter			
50 l. bin		•	•
Stainless steel container & filter chamber			
L-class hazardous dust approval	•	•	•
Main filter clogged indicator (electronic)	•	•	•
Automatic stopping for solids			
Grid and valve			
Fully in stainless steel			
Plastic bag system			
Suitable for liquids			
Longopac® system			

Model	S3 L100 LC L GV CC	S3 L100 LC L GV CC UKP	S3 L100 LC L GV CC 2X
Ref. no.	4010300267	4010300268	4010300330

## PRODUCT FEATURES

Manual filter shaker	•	•	•
Electrical filter shaker			
Cyclone system	•		•
Stainless steel container			
M-class hazardous dust approval			
H-class hazardous dust approval			
Uk model		•	



## 3 motor single phase industrial vacuum cleaner for hazardous dust

Model	S3 L100 LC L GV CC	S3 L100 LC L GV CC UKP	S3 L100 LC L GV CC 2X
Ref. no.	4010300267	4010300268	4010300330

## PRODUCT FEATURES

Power connected indicator	•	•	•
HEPA full indicator (electronic)			
HEPA (H14) upstream filtration			
100 l. bin	•	•	•
Automatic shut-off for liquid	•	•	•
M class filter			
50 l. bin			
Stainless steel container & filter chamber			•
L-class hazardous dust approval	•	•	•
Main filter clogged indicator (electronic)	•	•	•
Automatic stopping for solids			
Grid and valve	•	•	•
Fully in stainless steel			
Plastic bag system			
Suitable for liquids			
Longopac® system			

Model	S3 L50 LC GV CC	S3 L50 LC L GV CC 3X	S3 L100 LC FM AU UKP
Ref. no.	4010300347	4010300363	4010300366

## PRODUCT FEATURES

Manual filter shaker	•	•	•
Electrical filter shaker			
Cyclone system	•	•	
Stainless steel container			
M-class hazardous dust approval			
H-class hazardous dust approval			
Uk model			•
Power connected indicator	•	•	•
HEPA full indicator (electronic)			•
HEPA (H14) upstream filtration			•
100 l. bin			•
Automatic shut-off for liquid		•	
M class filter			•
50 l. bin	•	•	



3 motor single phase industrial vacuum cleaner for hazardous dust

Model	S3 L50 LC GV CC	S3 L50 LC L GV CC 3X	S3 L100 LC FM AU UKP
Ref. no.	4010300347	4010300363	4010300366

PRODUCT FEATURES

Stainless steel container & filter chamber			
L-class hazardous dust approval	•	•	•
Main filter clogged indicator (electronic)	•	•	•
Automatic stopping for solids			
Grid and valve	•	•	
Fully in stainless steel		•	
Plastic bag system			
Suitable for liquids			
Longopac® system			

Model	S3 L50 LC FM AU	S3 L50 LC PBS AU UKP	S3 L100 LC L GV CC AU UKP
Ref. no.	4010300349	4010300374	4010300401

PRODUCT FEATURES

Manual filter shaker	•	•	•
Electrical filter shaker			
Cyclone system			•
Stainless steel container			
M-class hazardous dust approval			
H-class hazardous dust approval			
Uk model		•	•
Power connected indicator	•	•	•
HEPA full indicator (electronic)	•	•	•
HEPA (H14) upstream filtration	•	•	•
100 l. bin			•
Automatic shut-off for liquid			
M class filter	•	•	
50 l. bin	•	•	
Stainless steel container & filter chamber			
L-class hazardous dust approval	•	•	•
Main filter clogged indicator (electronic)	•	•	•
Automatic stopping for solids			
Grid and valve			•
Fully in stainless steel			
Plastic bag system			



3 motor single phase industrial vacuum cleaner for hazardous dust

Model	S3 L50 LC FM AU	S3 L50 LC PBS AU UKP	S3 L100 LC L GV CC AU UKP
Ref. no.	4010300349	4010300374	4010300401

PRODUCT FEATURES

Suitable for liquids  
Longopac® system

Model	S3 L100 LC L GV CC AU V110 UKP	S3 MC LP UKP	S3 HC LP UKP
Ref. no.	4010300427	4010300434	4010300436

PRODUCT FEATURES

Manual filter shaker	•	•	•
Electrical filter shaker			
Cyclone system	•		
Stainless steel container			
M-class hazardous dust approval		•	
H-class hazardous dust approval			•
Uk model	•	•	•
Power connected indicator	•	•	•
HEPA full indicator (electronic)	•		•
HEPA (H14) upstream filtration	•		•
100 l. bin	•		
Automatic shut-off for liquid			
M class filter		•	•
50 l. bin		•	•
Stainless steel container & filter chamber			
L-class hazardous dust approval	•		
Main filter clogged indicator (electronic)	•	•	•
Automatic stopping for solids			
Grid and valve	•		
Fully in stainless steel			
Plastic bag system			
Suitable for liquids			
Longopac® system		•	•



## 3 motor single phase industrial vacuum cleaner for hazardous dust

Model	S3 HC LP V110 UKP	S3CB L100 LC FM	S3CB L100 LC FM V110 UKP
Ref. no.	4010300437	4010300474	4010300478

## PRODUCT FEATURES

Manual filter shaker	•	•	•
Electrical filter shaker			
Cyclone system			
Stainless steel container			
M-class hazardous dust approval			
H-class hazardous dust approval	•		
Uk model	•		•
Power connected indicator	•	•	•
HEPA full indicator (electronic)	•		
HEPA (H14) upstream filtration	•		
100 l. bin		•	•
Automatic shut-off for liquid			
M class filter	•	•	•
50 l. bin	•		
Stainless steel container & filter chamber			
L-class hazardous dust approval		•	•
Main filter clogged indicator (electronic)	•	•	•
Automatic stopping for solids			
Grid and valve			
Fully in stainless steel			
Plastic bag system			
Suitable for liquids			
Longopac® system	•		

Technical specifications	S3 L100 LC	S3 L100 LC UKP	S3 L100 LC V110 UKP
Voltage (V)	230	230	110
Frequency (Hz)	50-60	50-60	50-60
IP protection class	44	44	44
Insulation class	I	I	I
Rated power (kW)	3	3	3
Airflow without hose (m³/h - l/m)	486 - 8100	486 - 8100	425 - 7080
Max. vacuum (kPa - mbar)	21.1 - 211	21.1 - 211	16.5 - 165
Sound pressure level (dB(A))	71	71	71
Container capacity (l)	100	100	100



## 3 motor single phase industrial vacuum cleaner for hazardous dust

Technical specifications	S3 L100 LC	S3 L100 LC UKP	S3 L100 LC V110 UKP
Main filter area (cm <sup>2</sup> )	19500	19500	19500
Inlet (mm)	70	70	70
Length x width x height (mm)	800x600x1580	800x600x1580	800x600x1580
Weight (kg)	71	71	71

Technical specifications	S3 L100 LC GV CC UKP	S3 L100 LC GV CC V110 UKP	S3 L50 LC
Voltage (V)	230	110	230
Frequency (Hz)	50-60	50-60	50-60
IP protection class	44	44	44
Insulation class	I	I	I
Rated power (kW)	3	3	3
Airflow without hose (m <sup>3</sup> /h - l/m)	486 - 8100	425 - 7080	486 - 8100
Max. vacuum (kPa - mbar)	21.1 - 211	16.5 - 165	21.1 - 211
Sound pressure level (dB(A))	71	71	71
Container capacity (l)	100	100	50
Main filter area (cm <sup>2</sup> )	19500	19500	19500
Inlet (mm)	70	70	70
Length x width x height (mm)	800x600x1580	800x600x1580	800x600x1300
Weight (kg)	71	71	68

Technical specifications	S3 L100 LC FM	S3 L100 LC AU	S3 L100 LC AU UKP
Voltage (V)	230	230	230
Frequency (Hz)	50-60	50-60	50-60
IP protection class	44	44	44
Insulation class	I	I	I
Rated power (kW)	3	3	3
Airflow without hose (m <sup>3</sup> /h - l/m)	486 - 8100	486 - 8100	486 - 8100
Max. vacuum (kPa - mbar)	21.1 - 211	21.1 - 211	21.1 - 211
Sound pressure level (dB(A))	71	71	71
Container capacity (l)	100	100	100
Main filter area (cm <sup>2</sup> )	19500	19500	19500
Inlet (mm)	70	70	70
Length x width x height (mm)	800x600x1580	800x600x1580	800x600x1580
Weight (kg)	71	71	71





## 3 motor single phase industrial vacuum cleaner for hazardous dust

Technical specifications	S3 L100 LC AU V110 UKP	S3 L50 LC AU	S3 L50 LC V110 UKP
Voltage (V)	110	230	110
Frequency (Hz)	50-60	50-60	50-60
IP protection class	44	44	44
Insulation class	I	I	I
Rated power (kW)	3	3	3
Airflow without hose (m <sup>3</sup> /h - l/m)	425 - 7080	486 - 8100	425 - 7080
Max. vacuum (kPa - mbar)	16.5 - 165	21.1 - 211	16.5 - 165
Sound pressure level (dB(A))	71	71	71
Container capacity (l)	100	50	50
Main filter area (cm <sup>2</sup> )	19500	19500	19500
Inlet (mm)	70	70	70
Length x width x height (mm)	800x600x1580	800x600x1300	800x600x1300
Weight (kg)	71	68	68

Technical specifications	S3 L100 LC L GV CC	S3 L100 LC L GV CC UKP	S3 L100 LC L GV CC 2X
Voltage (V)	230	230	230
Frequency (Hz)	50-60	50-60	50-60
IP protection class	44	44	44
Insulation class	I	I	I
Rated power (kW)	3	3	3
Airflow without hose (m <sup>3</sup> /h - l/m)	486 - 8100	486 - 8100	486 - 8100
Max. vacuum (kPa - mbar)	21.1 - 211	21.1 - 211	21.1 - 211
Sound pressure level (dB(A))	71	71	71
Container capacity (l)	100	100	100
Main filter area (cm <sup>2</sup> )	19500	19500	19500
Inlet (mm)	70	70	70
Length x width x height (mm)	800x600x1580	800x600x1580	800x600x1580
Weight (kg)	71	71	71

Technical specifications	S3 L50 LC GV CC	S3 L50 LC L GV CC 3X	S3 L100 LC FM AU UKP
Voltage (V)	230	230	230
Frequency (Hz)	50-60	50-60	50-60
IP protection class	44	44	44
Insulation class	I	I	I
Rated power (kW)	3	3	3
Airflow without hose (m <sup>3</sup> /h - l/m)	486 - 8100	486 - 8100	486 - 8100
Max. vacuum (kPa - mbar)	21.1 - 211	21.1 - 211	21.1 - 211



## 3 motor single phase industrial vacuum cleaner for hazardous dust

Technical specifications	S3 L50 LC GV CC	S3 L50 LC L GV CC 3X	S3 L100 LC FM AU UKP
Sound pressure level (dB(A))	71	71	71
Container capacity (l)	50	50	100
Main filter area (cm <sup>2</sup> )	19500	19500	19500
Inlet (mm)	70	70	70
Length x width x height (mm)	800x600x1300	800x600x1300	800x600x1580
Weight (kg)	68	68	71

Technical specifications	S3 L50 LC FM AU	S3 L50 LC PBS AU UKP	S3 L100 LC L GV CC AU UKP
Voltage (V)	230	230	230
Frequency (Hz)	50-60	50-60	50-60
IP protection class	44	44	44
Insulation class	I	I	I
Rated power (kW)	3	3	3
Airflow without hose (m <sup>3</sup> /h - l/m)	486 - 8100	486 - 8100	486 - 8100
Max. vacuum (kPa - mbar)	21.1 - 211	21.1 - 211	21.1 - 211
Sound pressure level (dB(A))	71	71	71
Container capacity (l)	50	50	100
Main filter area (cm <sup>2</sup> )	19500	19500	19500
Inlet (mm)	70	70	70
Length x width x height (mm)	800x600x1300	800x600x1300	800x600x1580
Weight (kg)	68	68	71



Technical specifications	S3 L100 LC L GV CC AU V110 UKP	S3 MC LP UKP	S3 HC LP UKP
Voltage (V)	110	230	230
Frequency (Hz)	50-60	50-60	50-60
IP protection class	44	44	44
Insulation class	I	I	I
Rated power (kW)	3	3	3
Airflow without hose (m <sup>3</sup> /h - l/m)	425 - 7080	486 - 8100	486 - 8100
Max. vacuum (kPa - mbar)	16.5 - 165	21.1 - 211	21.1 - 211
Sound pressure level (dB(A))	71	71	71
Container capacity (l)	100	Longopac	Longopac
Main filter area (cm <sup>2</sup> )	19500	19500	19500
Inlet (mm)	70	70	70
Length x width x height (mm)	800x600x1580	800x600x1500	800x600x1500
Weight (kg)	71	76	76



3 motor single phase industrial vacuum cleaner for hazardous dust











Technical specifications	S3 HC LP V110 UKP	S3CB L100 LC FM	S3CB L100 LC FM V110 UKP
Voltage (V)	110	230	110
Frequency (Hz)	50-60	50-60	50-60
IP protection class	44	44	44
Insulation class	I	I	I
Rated power (kW)	3	3	3
Airflow without hose (m³/h - l/m)	425 - 7080	486 - 8100	425 - 7080
Max. vacuum (kPa - mbar)	16.5 - 165	21.1 - 211	16.5 - 165
Sound pressure level (dB(A))	71	71	71
Container capacity (l)	Longopac	100	100
Main filter area (cm²)	19500	19500	19500
Inlet (mm)	70	70	70
Length x width x height (mm)	800x600x1500	800x600x1580	800x600x1580
Weight (kg)	76	71	71

● Standard equipment, ○ Supplementary accessories, □ Mountable equipment













Accessories		Ref. no.	Min. required	S3 L100 LC	S3 L100 LC UKP	S3 L100 LC V110 UKP
<b>Filter</b>						
	ABSOLUTE FILTER KIT M.125/1216	Z5 60357	1	○	○	○
	KIT STAR FILTER D460 L CLASS	40000338	1	○	○	○
	SAFETY FILTER BAG 460MM STD W SAFETY BLT	4084001244	1	○	○	○
	STAR FILTER KIT D460 M CLASS	40000492	1	○	○	○
<b>Other</b>						
	BRACKET EMPTYING BELT D460 COMPLETE	Z5 36074	1	○	○	○
	EMPTYING BELT D460 COMPLETE	Z5 36073	1	○	○	○
	HARMONIC SPRINGPIN LINK	Z7 20328	1	○	○	○
	KIT MECANICAL FLOAT S3B SS	4056000519	1	○	○	○
	TRIM BASKET KIT D460 L100	40000915	1	○	○	○
<b>Bag</b>						
	5PCS PAPER BAGS GS82	81584000	1	○	○	○
<b>Option</b>						
	EXTRACT CYCLONE D460 FE COMPLETE	Z5 60109	1	○	○	○
	KIT LIFTING MS2-S3	4056000493	1	○	○	○
	KIT LIQUIDS M.S3	4056000498	1	○	○	○



## 3 motor single phase industrial vacuum cleaner for hazardous dust













Accessories		Ref. no.	Min. required	S3 L100 LC	S3 L100 LC UKP	S3 L100 LC V110 UKP
	KIT STAFFA SOLLEVAMENTO CONT. MODELLI CT	4056000394	1	○	○	○
<b>Vac Nozzle Fixed</b>						
	KIT FIX NOZZLE MM600 M.S2-S3	4056000487	1	○	○	○
<b>Assembly</b>						
	GRID AND VALVE D460 FE COMPLETE	Z5 60034	1	○	○	○
<b>Accessory Kit</b>						
	KIT AC.D50 EQUIPMENTS CLEANING	Z7 24156	1	○	○	○
	KIT AC.D50 INDUSTRIAL CLEANING	Z7 24151	1	○	○	○
	KIT ACC.D.50 GENERAL CLEANING	Z7 24146	1	○	○	○
	KIT INLET FOR PAPER BAG D70 SS WITH	Z5 60375	1	○	○	○
	KIT INLET X PAPER BAG D.70 COMP.WITH	Z5 60351	1	○	○	○
<b>Vacuum Hose and Connection</b>						
	BENT CONNECTION D40 FE	Z7 21013	1	○	○	○
	BENT CONNECTION D50 FE	Z7 21012	1	○	○	○
	BENT CONNECTION D50 INOX	Z7 21034	1	○	○	○
	BENT CONNECTION D50/40 Z.PLT.	Z7 22015	1	○	○	○
	BENT CONNECTION D70 FE	Z7 21032	1	○	○	○
	CONNECTION JOINT D40 FE	Z7 21004	1	○	○	○

## 3 motor single phase industrial vacuum cleaner for hazardous dust



Accessories	Ref. no.	Min. required	S3 L100 LC	S3 L100 LC UKP	S3 L100 LC V110 UKP
 CONNECTION JOINT D50 FE	Z7 21002	1	○	○	○
 CONNECTION JOINT D50 INOX	Z7 22241	1	○	○	○
 CONNECTION JOINT D70 FE	Z7 21000	1	○	○	○
 CONNECTION JOINT D70 INOX	Z7 22242	1	○	○	○
 CONNECTION TUBE D70 INOX	Z7 22231	0	○	○	○
 CONNECTION TUBE D70 STEEL	Z7 21001	1	○	○	○
 QUICK COUPLING D40 FE COMPLETE	Z7 22186	1	○	○	○
 QUICK COUPLING D50 FE COMPLETE	Z7 22187	1	○	○	○
 REDUCER D70/40 FE	Z7 22002	1	○	○	○
 REDUCER IRON D70/50	Z7 22001	1	○	○	○
 REDUCER REGULATION D70/50 COMPLETE	Z7 22162	1	○	○	○
 REDUCER REGULATION D.70/40 COMPLETE	Z7 22164	1	○	○	○
<b>Cone Nozzle</b>					















## 3 motor single phase industrial vacuum cleaner for hazardous dust

Accessories		Ref. no.	Min. required	S3 L100 LC	S3 L100 LC UKP	S3 L100 LC V110 UKP
	CONIC END D40/50/20 COMPLETE	Z7 22142	1	○	○	○
	CONIC END D50/20 COMPLETE	Z7 22141	1	○	○	○
	CONIC TUBE D40 RUBBER	Z7 21011	1	○	○	○
	CONIC TUBE D50 RUBBER	Z7 21010	1	○	○	○
	CONIC TUBE D70 RUBBER	Z7 21009	1	○	○	○
<b>Crevice Nozzle</b>						
	CURVED FLAT LANCE D50 FE	Z7 21075	1	○	○	○
	CURVED FLAT LANCE D70 MM1000 PVC	Z7 24012	1	○	○	○
	FLAT LANCE D40 MM500 PVC	Z7 24014	1	○	○	○
	FLAT LANCE D40 ZINC PLT.	Z7 21027	1	○	○	○
	FLAT LANCE D50 MM500 PVC	Z7 24013	1	○	○	○
	FLAT LANCE D50 ZINC PLT.	Z7 21026	1	○	○	○
	FLAT LANCE D50/40 ZINC PLT.	Z7 22021	1	○	○	○

## 3 motor single phase industrial vacuum cleaner for hazardous dust


Accessories		Ref. no.	Min. required	S3 L100 LC	S3 L100 LC UKP	S3 L100 LC V110 UKP
	FLAT LANCE D70 ZINC PLT.	Z7 21028	1	○	○	○
	FLAT LANCE DIAL D40 FE COMP.DIAL NYLON	Z7 22088	1	○	○	○
	FLAT LANCE DIAL D40 FE COMPLETE DIAL	Z7 22024	1	○	○	○
	FLAT LANCE DIAL D50 FE COMP.DIAL NYLON	Z7 22089	1	○	○	○
	FLAT LANCE DIAL D50 FE COMPLETE DIAL	Z7 22023	1	○	○	○
	GREY NBR NOZZLE D50 120MM	Z7 21030	1	○	○	○
	SCRAPING SUCKER D40 FE	Z7 22033	1	○	○	○
	SCRAPING SUCKER D40 INOX	Z7 22277	1	○	○	○
	SCRAPING SUCKER D50 FE	Z7 22034	1	○	○	○
	SCRAPING SUCKER D50 INOX	Z7 22278	1	○	○	○
	SCRAPING SUCKER D70 MM 200	Z7 22090	1	○	○	○
<b>Hose and Connection</b>						
	BENT CONNECTION D40 INOX	Z7 21033	1	○	○	○

## 3 motor single phase industrial vacuum cleaner for hazardous dust


Accessories		Ref. no.	Min. required	S3 L100 LC	S3 L100 LC UKP	S3 L100 LC V110 UKP
	CONNECTION JOINT D40 INOX	Z7 22240	1	○	○	○
	G.REDUCER D70/40 INOX COMPLETE	Z7 22235	0	○	○	○
	REDUCER D70/40 INOX	Z7 22224	1	○	○	○
	REDUCER D70/50 INOX	Z7 22225	1	○	○	○
	REG.REDUCER D70/50 INOX COMPLETE	Z7 22236	0	○	○	○
	TIE D40-60	Z8 40040	1	○	○	○
<b>Extension Tube</b>						
	ALUMINIUM EXTENSION D50 MT1 INLET PIN	Z7 22385	1	○	○	○
	EXTENSION D40 MT.1 ALUMINIUM COMPLETE	Z7 22008	1	○	○	○
	EXTENSION D40 MT.2 ALUMINIUM COMPLETE	Z7 22007	1	○	○	○
	EXTENSION D40 MT.3 ALUMINIUM COMPLETE	Z7 22006	1	○	○	○
	EXTENSION D50 MT.1 ALUMINIUM COMPLETE	Z7 22005	1	○	○	○
	EXTENSION D50 MT.2 ALUMINIUM COMPLETE	Z7 22004	1	○	○	○















## 3 motor single phase industrial vacuum cleaner for hazardous dust

Accessories		Ref. no.	Min. required	S3 L100 LC	S3 L100 LC UKP	S3 L100 LC V110 UKP
	EXTENSION D50 MT.3 ALUMINIUM COMPLETE	Z7 22003	1	○	○	○
	HANDGRIP D40 ALUMINIUM COMPLETE	Z7 22026	1	○	○	○
	HANDGRIP D40 CHROME PLT. COMPLETE	Z7 22121	1	○	○	○
	HANDGRIP D50 ALUMINIUM COMPLETE	Z7 22025	1	○	○	○
	HANDGRIP D50 CHROME PLT. COMPLETE	Z7 22122	1	○	○	○
<b>Vac Nozzle Wet</b>						
	LIQ.SUCKER D40 MM500 FE COMPLETE	Z7 22168	1	○	○	○
	LIQ.SUCKER D50 MM500 FE COMPLETE	Z7 22167	1	○	○	○
	LIQUIDS SUCKER D40 MM400 FE COMPLETE	Z7 22028	1	○	○	○
	LIQUIDS SUCKER D50 MM400 FE COMPLETE	Z7 22027	1	○	○	○
<b>Vac Nozzle Dry</b>						
	AUTOBUS SUCKER D50 200 AL. COMPLETE	Z7 22170	1	○	○	○
	BRUSH D40 MM220 30 COMPLETE	Z7 22193	1	○	○	○

## 3 motor single phase industrial vacuum cleaner for hazardous dust

Accessories	Ref. no.	Min. required	S3 L100 LC	S3 L100 LC UKP	S3 L100 LC V110 UKP
 BRUSH D40 MM220 90 COMPLETE	Z7 22042	1	○	○	○
 BRUSH D40 MM300 30 COMPLETE	Z7 22194	1	○	○	○
 BRUSH D40 MM300 90 COMPLETE	Z7 22043	1	○	○	○
 BRUSH D40 MM400 30 COMPLETE	Z7 22195	1	○	○	○
 BRUSH D40 MM400 90 COMPLETE	Z7 22044	1	○	○	○
 BRUSH D50 MM220 30 COMPLETE	Z7 22196	1	○	○	○
 BRUSH D50 MM220 90 COMPLETE	Z7 22038	1	○	○	○
 BRUSH D50 MM300 30 COMPLETE	Z7 22197	1	○	○	○
 BRUSH D50 MM300 90 COMPLETE	Z7 22039	1	○	○	○
 BRUSH D50 MM400 30 COMPLETE	Z7 22198	1	○	○	○
 BRUSH D50 MM400 90 COMPLETE	Z7 22040	1	○	○	○
 MOB.SUCKER D50 MM500 FE COMPLETE	Z7 22147	1	○	○	○












## 3 motor single phase industrial vacuum cleaner for hazardous dust

Accessories	Ref. no.	Min. required	S3 L100 LC	S3 L100 LC UKP	S3 L100 LC V110 UKP
 MOB.SUCKER STRIP D40 MM300 FE COMPLETE	Z7 22174	1	○	○	○
 MOB.SUCKER STRIP D40 MM400 FE COMPLETE	Z7 22138	1	○	○	○
 MOB.SUCKER STRIP D50 MM300 FE COMPLETE	Z7 22175	1	○	○	○
 MOB.SUCKER STRIP D50 MM400 FE COMPLETE	Z7 22137	1	○	○	○
 MOB.SUCKER STRIP D50 MM500 FE COMPLETE	Z7 22148	1	○	○	○
 MOBILE SUCKER D40 MM300 FE COMPLETE	Z7 22171	1	○	○	○
 MOBILE SUCKER D40 MM400 FE COMPLETE	Z7 22030	1	○	○	○
 MOBILE SUCKER D50 MM300 FE COMPLETE	Z7 22172	1	○	○	○
 MOBILE SUCKER D50 MM400 FE COMPLETE	Z7 22029	1	○	○	○
 SUCKER D40 MM400 ALUMINIUM	Z7 22031	1	○	○	○
 SUCKER D50 MM400 ALUMINIUM	Z7 22032	1	○	○	○
 SUCKER X FURNACES D40 MM400 FE COMPLETE	Z7 22272	1	○	○	○



## 3 motor single phase industrial vacuum cleaner for hazardous dust

Accessories		Ref. no.	Min. required	S3 L100 LC	S3 L100 LC UKP	S3 L100 LC V110 UKP
	SUCKER X FURNACES D50 MM400 FE COMPLETE	Z7 22273	1	○	○	○
<b>Round Brush Nozzle</b>						
	PAINTBRUSH D50/100 BRISTLES COMPLETE	Z7 22047	1	○	○	○
	PAINTBRUSH D50/100 STEEL COMPLETE	Z7 22048	1	○	○	○
<b>Hose Vacuum Cleaner</b>						
	AIR HOSE D40MT3+SLEEVES	Z7 22049	1	○	○	○
	AIR HOSE D40MT5+SLEEVES	Z7 22362	1	○	○	○
	AIR HOSE D50MT3+SLEEVES	Z7 22062	1	○	○	○
	AIR HOSE D50MT5+SLEEVES	Z7 22363	1	○	○	○
	AIR HOSE D70MT3+SLEEVES	Z7 22063	1	○	○	○
	AIR HOSE D70MT5+SLEEVES	Z7 22364	1	○	○	○
	FLEX HOSE D40MT3+SLEEVES	Z7 22150	1	○	○	○
	FLEX HOSE D40MT5+SLEEVES	Z7 22360	1	○	○	○



## 3 motor single phase industrial vacuum cleaner for hazardous dust

Accessories		Ref. no.	Min. required	S3 L100 LC	S3 L100 LC UKP	S3 L100 LC V110 UKP
	FLEX HOSE D50MT3+SLEEVES	Z7 22151	1	○	○	○
	FLEX HOSE D50MT5+SLEEVES	Z7 22361	1	○	○	○
	POLYURETHANE HOSE D40 3M +SLEEVES	Z7 22297	1	○	○	○
	POLYURETHANE HOSE D40 5M +SLEEVES	Z7 22365	1	○	○	○
	POLYURETHANE HOSE D50 3M +SLEEVES	Z7 22298	1	○	○	○
	POLYURETHANE HOSE D50 5M +SLEEVES	Z7 22366	1	○	○	○
	POLYURETHANE HOSE D70 3M +SLEEVES	Z7 22299	1	○	○	○
	POLYURETHANE HOSE D70 5M +SLEEVES	Z7 22367	1	○	○	○
<b>Pipe Cleaner Nozzle</b>						
	CURVED BRUSH FOR PIPES D40/100 FE COMPL	Z7 22132	1	○	○	○
	CURVED BRUSH FOR PIPES D50/100 FE COMPL	Z7 22131	1	○	○	○
<b>Nozzle</b>						
	LIQ.SUCKER D50 MM400 INOX COMPLETE	Z7 22294	1	○	○	○

## 3 motor single phase industrial vacuum cleaner for hazardous dust










Accessories		Ref. no.	Min. required	S3 L100 LC	S3 L100 LC UKP	S3 L100 LC V110 UKP
	LIQUIDS SUCKER D40 MM400 INOX COMPLETE	Z7 22296	1	○	○	○
	PACK10 RUBBERS FIX.NOZZLE MM600-700	Z8 20297	1	○	○	○
	PACK 10 STRIP MOBILE S. MM.400	Z8 23040	1	○	○	○
	PACK 10 STRIP MOBILE S. MM.500	Z8 23041	1	○	○	○
	PACK OF 10 RUBBERS 400 20086	Z8 20295	1	○	○	○

● Standard equipment, ○ Supplementary accessories, □ Mountable equipment













Accessories		Ref. no.	Min. required	S3 L100 LC GV CC UKP	S3 L100 LC GV CC V110 UKP	S3 L50 LC
<b>Filter</b>						
	ABSOLUTE FILTER KIT M.125/1216	Z5 60357	1	○	○	○
	KIT STAR FILTER D460 L CLASS	40000338	1	○	○	○
	SAFETY FILTER BAG 460MM STD W SAFETY BLT	4084001244	1	○	○	○
	STAR FILTER KIT D460 M CLASS	40000492	1	○	○	○
<b>Other</b>						
	BRACKET EMPTYING BELT D460 COMPLETE	Z5 36074	1	○	○	○
	EMPTYING BELT D460 COMPLETE	Z5 36073	1	○	○	○
	HARMONIC SPRINGPIN LINK	Z7 20328	1	○	○	○
	KIT MECANICAL FLOAT S3B SS	4056000519	1	○	○	○
	TRIM BASKET KIT D460 L100	40000915	1	○	○	○
<b>Bag</b>						
	5PCS PAPER BAGS GS82	81584000	1	○	○	○
<b>Option</b>						
	EXTRACT CYCLONE D460 FE COMPLETE	Z5 60109	1	○	○	○
	KIT LIFTING MS2-S3	4056000493	1	○	○	○
	KIT LIQUIDS M.S3	4056000498	1	○	○	○
	KIT STAFFA SOLLEVAMENTO CONT. MODELLI CT	4056000394	1	○	○	○
<b>Vac Nozzle Fixed</b>						



## 3 motor single phase industrial vacuum cleaner for hazardous dust












Accessories		Ref. no.	Min. required	S3 L100 LC GV CC UKP	S3 L100 LC GV CC V110 UKP	S3 L50 LC
	KIT FIX NOZZLE MM600 M.S2-S3	4056000487	1	○	○	○
<b>Assembly</b>						
	GRID AND VALVE D460 FE COMPLETE	Z5 60034	1	●	○	○
<b>Accessory Kit</b>						
	KIT AC.D50 EQUIPMENTS CLEANING	Z7 24156	1	○	○	○
	KIT AC.D50 INDUSTRIAL CLEANING	Z7 24151	1	○	○	○
	KIT ACC.D.50 GENERAL CLEANING	Z7 24146	1	○	○	○
	KIT INLET FOR PAPER BAG D70 SS WITH	Z5 60375	1	○	○	○
	KIT INLET X PAPER BAG D.70 COMP.WITH	Z5 60351	1	○	○	○
<b>Vacuum Hose and Connection</b>						
	BENT CONNECTION D40 FE	Z7 21013	1	○	○	○
	BENT CONNECTION D50 FE	Z7 21012	1	○	○	○
	BENT CONNECTION D50 INOX	Z7 21034	1	○	○	○
	BENT CONNECTION D50/40 Z.PLT.	Z7 22015	1	○	○	○
	BENT CONNECTION D70 FE	Z7 21032	1	○	○	○
	CONNECTION JOINT D40 FE	Z7 21004	1	○	○	○

## 3 motor single phase industrial vacuum cleaner for hazardous dust

	Accessories	Ref. no.	Min. required	S3 L100 LC GV CC UKP	S3 L100 LC GV CC V110 UKP	S3 L50 LC
	CONNECTION JOINT D50 FE	Z7 21002	1	○	○	○
	CONNECTION JOINT D50 INOX	Z7 22241	1	○	○	○
	CONNECTION JOINT D70 FE	Z7 21000	1	○	○	○
	CONNECTION JOINT D70 INOX	Z7 22242	1	○	○	○
	CONNECTION TUBE D70 INOX	Z7 22231	0	○	○	○
	CONNECTION TUBE D70 STEEL	Z7 21001	1	○	○	○
	QUICK COUPLING D40 FE COMPLETE	Z7 22186	1	○	○	○
	QUICK COUPLING D50 FE COMPLETE	Z7 22187	1	○	○	○
	REDUCER D70/40 FE	Z7 22002	1	○	○	○
	REDUCER IRON D70/50	Z7 22001	1	○	○	○
	REDUCER REGULATION D70/50 COMPLETE	Z7 22162	1	○	○	○
	REDUCER REGULATION D.70/40 COMPLETE	Z7 22164	1	○	○	○



## 3 motor single phase industrial vacuum cleaner for hazardous dust












Accessories		Ref. no.	Min. required	S3 L100 LC GV CC UKP	S3 L100 LC GV CC V110 UKP	S3 L50 LC
<b>Cone Nozzle</b>						
	CONIC END D40/50/20 COMPLETE	Z7 22142	1	○	○	○
	CONIC END D50/20 COMPLETE	Z7 22141	1	○	○	○
	CONIC TUBE D40 RUBBER	Z7 21011	1	○	○	○
	CONIC TUBE D50 RUBBER	Z7 21010	1	○	○	○
	CONIC TUBE D70 RUBBER	Z7 21009	1	○	○	○
<b>Crevice Nozzle</b>						
	CURVED FLAT LANCE D50 FE	Z7 21075	1	○	○	○
	CURVED FLAT LANCE D70 MM1000 PVC	Z7 24012	1	○	○	○
	FLAT LANCE D40 MM500 PVC	Z7 24014	1	○	○	○
	FLAT LANCE D40 ZINC PLT.	Z7 21027	1	○	○	○
	FLAT LANCE D50 MM500 PVC	Z7 24013	1	○	○	○
	FLAT LANCE D50 ZINC PLT.	Z7 21026	1	○	○	○

## 3 motor single phase industrial vacuum cleaner for hazardous dust












	Accessories	Ref. no.	Min. required	S3 L100 LC GV CC UKP	S3 L100 LC GV CC V110 UKP	S3 L50 LC
	FLAT LANCE D50/40 ZINC PLT.	Z7 22021	1	○	○	○
	FLAT LANCE D70 ZINC PLT.	Z7 21028	1	○	○	○
	FLAT LANCE DIAL D40 FE COMP.DIAL NYLON	Z7 22088	1	○	○	○
	FLAT LANCE DIAL D40 FE COMPLETE DIAL	Z7 22024	1	○	○	○
	FLAT LANCE DIAL D50 FE COMP.DIAL NYLON	Z7 22089	1	○	○	○
	FLAT LANCE DIAL D50 FE COMPLETE DIAL	Z7 22023	1	○	○	○
	GREY NBR NOZZLE D50 120MM	Z7 21030	1	○	○	○
	SCRAPING SUCKER D40 FE	Z7 22033	1	○	○	○
	SCRAPING SUCKER D40 INOX	Z7 22277	1	○	○	○
	SCRAPING SUCKER D50 FE	Z7 22034	1	○	○	○
	SCRAPING SUCKER D50 INOX	Z7 22278	1	○	○	○
	SCRAPING SUCKER D70 MM 200	Z7 22090	1	○	○	○



## 3 motor single phase industrial vacuum cleaner for hazardous dust

Accessories		Ref. no.	Min. required	S3 L100 LC GV CC UKP	S3 L100 LC GV CC V110 UKP	S3 L50 LC
<b>Hose and Connection</b>						
	BENT CONNECTION D40 INOX	Z7 21033	1	○	○	○
	CONNECTION JOINT D40 INOX	Z7 22240	1	○	○	○
	G.REDUCER D70/40 INOX COMPLETE	Z7 22235	0	○	○	○
	REDUCER D70/40 INOX	Z7 22224	1	○	○	○
	REDUCER D70/50 INOX	Z7 22225	1	○	○	○
	REG.REDUCER D70/50 INOX COMPLETE	Z7 22236	0	○	○	○
	TIE D40-60	Z8 40040	1	○	○	○
<b>Extension Tube</b>						
	ALUMINIUM EXTENSION D50 MT1 INLET PIN	Z7 22385	1	○	○	○
	EXTENSION D40 MT.1 ALUMINIUM COMPLETE	Z7 22008	1	○	○	○
	EXTENSION D40 MT.2 ALUMINIUM COMPLETE	Z7 22007	1	○	○	○
	EXTENSION D40 MT.3 ALUMINIUM COMPLETE	Z7 22006	1	○	○	○

## 3 motor single phase industrial vacuum cleaner for hazardous dust

	Accessories	Ref. no.	Min. required	S3 L100 LC GV CC UKP	S3 L100 LC GV CC V110 UKP	S3 L50 LC
	EXTENSION D50 MT.1 ALUMINIUM COMPLETE	Z7 22005	1	○	○	○
	EXTENSION D50 MT.2 ALUMINIUM COMPLETE	Z7 22004	1	○	○	○
	EXTENSION D50 MT.3 ALUMINIUM COMPLETE	Z7 22003	1	○	○	○
	HANDGRIP D40 ALUMINIUM COMPLETE	Z7 22026	1	○	○	○
	HANDGRIP D40 CHROME PLT. COMPLETE	Z7 22121	1	○	○	○
	HANDGRIP D50 ALUMINIUM COMPLETE	Z7 22025	1	○	○	○
	HANDGRIP D50 CHROME PLT. COMPLETE	Z7 22122	1	○	○	○
<b>Vac Nozzle Wet</b>						
	LIQ.SUCKER D40 MM500 FE COMPLETE	Z7 22168	1	○	○	○
	LIQ.SUCKER D50 MM500 FE COMPLETE	Z7 22167	1	○	○	○
	LIQUIDS SUCKER D40 MM400 FE COMPLETE	Z7 22028	1	○	○	○
	LIQUIDS SUCKER D50 MM400 FE COMPLETE	Z7 22027	1	○	○	○
<b>Vac Nozzle Dry</b>						

## 3 motor single phase industrial vacuum cleaner for hazardous dust

	Accessories	Ref. no.	Min. required	S3 L100 LC GV CC UKP	S3 L100 LC GV CC V110 UKP	S3 L50 LC
	AUTOBUS SUCKER D50 200 AL. COMPLETE	Z7 22170	1	○	○	○
	BRUSH D40 MM220 30 COMPLETE	Z7 22193	1	○	○	○
	BRUSH D40 MM220 90 COMPLETE	Z7 22042	1	○	○	○
	BRUSH D40 MM300 30 COMPLETE	Z7 22194	1	○	○	○
	BRUSH D40 MM300 90 COMPLETE	Z7 22043	1	○	○	○
	BRUSH D40 MM400 30 COMPLETE	Z7 22195	1	○	○	○
	BRUSH D40 MM400 90 COMPLETE	Z7 22044	1	○	○	○
	BRUSH D50 MM220 30 COMPLETE	Z7 22196	1	○	○	○
	BRUSH D50 MM220 90 COMPLETE	Z7 22038	1	○	○	○
	BRUSH D50 MM300 30 COMPLE	Z7 22197	1	○	○	○
	BRUSH D50 MM300 90 COMPLETE	Z7 22039	1	○	○	○
	BRUSH D50 MM400 30 COMPLETE	Z7 22198	1	○	○	○



## 3 motor single phase industrial vacuum cleaner for hazardous dust












	Accessories	Ref. no.	Min. required	S3 L100 LC GV CC UKP	S3 L100 LC GV CC V110 UKP	S3 L50 LC
	BRUSH D50 MM400 90 COMPLETE	Z7 22040	1	○	○	○
	MOB.SUCKER D50 MM500 FE COMPLETE	Z7 22147	1	○	○	○
	MOB.SUCKER STRIP D40 MM300 FE COMPLETE	Z7 22174	1	○	○	○
	MOB.SUCKER STRIP D40 MM400 FE COMPLETE	Z7 22138	1	○	○	○
	MOB.SUCKER STRIP D50 MM300 FE COMPLETE	Z7 22175	1	○	○	○
	MOB.SUCKER STRIP D50 MM400 FE COMPLETE	Z7 22137	1	○	○	○
	MOB.SUCKER STRIP D50 MM500 FE COMPLETE	Z7 22148	1	○	○	○
	MOBILE SUCKER D40 MM300 FE COMPLETE	Z7 22171	1	○	○	○
	MOBILE SUCKER D40 MM400 FE COMPLETE	Z7 22030	1	○	○	○
	MOBILE SUCKER D50 MM300 FE COMPLETE	Z7 22172	1	○	○	○
	MOBILE SUCKER D50 MM400 FE COMPLETE	Z7 22029	1	○	○	○
	SUCKER D40 MM400 ALUMINIUM	Z7 22031	1	○	○	○



## 3 motor single phase industrial vacuum cleaner for hazardous dust





Accessories	Ref. no.	Min. required	S3 L100 LC GV CC UKP	S3 L100 LC GV CC V110 UKP	S3 L50 LC
 SUCKER D50 MM400 ALUMINIUM	Z7 22032	1	○	○	○
 SUCKER X FURNACES D40 MM400 FE COMPLETE	Z7 22272	1	○	○	○
 SUCKER X FURNACES D50 MM400 FE COMPLETE	Z7 22273	1	○	○	○
<b>Round Brush Nozzle</b>					
 PAINTBRUSH D50/100 BRISTLES COMPLETE	Z7 22047	1	○	○	○
 PAINTBRUSH D50/100 STEEL COMPLETE	Z7 22048	1	○	○	○
<b>Hose Vacuum Cleaner</b>					
 AIR HOSE D40MT3+SLEEVES	Z7 22049	1	○	○	○
 AIR HOSE D40MT5+SLEEVES	Z7 22362	1	○	○	○
 AIR HOSE D50MT3+SLEEVES	Z7 22062	1	○	○	○
 AIR HOSE D50MT5+SLEEVES	Z7 22363	1	○	○	○
 AIR HOSE D70MT3+SLEEVES	Z7 22063	1	○	○	○
 AIR HOSE D70MT5+SLEEVES	Z7 22364	1	○	○	○

## 3 motor single phase industrial vacuum cleaner for hazardous dust



	Accessories	Ref. no.	Min. required	S3 L100 LC GV CC UKP	S3 L100 LC GV CC V110 UKP	S3 L50 LC
	FLEX HOSE D40MT3+SLEEVES	Z7 22150	1	○	○	○
	FLEX HOSE D40MT5+SLEEVES	Z7 22360	1	○	○	○
	FLEX HOSE D50MT3+SLEEVES	Z7 22151	1	○	○	○
	FLEX HOSE D50MT5+SLEEVES	Z7 22361	1	○	○	○
	POLYURETHANE HOSE D40 3M +SLEEVES	Z7 22297	1	○	○	○
	POLYURETHANE HOSE D40 5M +SLEEVES	Z7 22365	1	○	○	○
	POLYURETHANE HOSE D50 3M +SLEEVES	Z7 22298	1	○	○	○
	POLYURETHANE HOSE D50 5M +SLEEVES	Z7 22366	1	○	○	○
	POLYURETHANE HOSE D70 3M +SLEEVES	Z7 22299	1	○	○	○
	POLYURETHANE HOSE D70 5M +SLEEVES	Z7 22367	1	○	○	○
<b>Pipe Cleaner Nozzle</b>						
	CURVED BRUSH FOR PIPES D40/100 FE COMPL	Z7 22132	1	○	○	○



## 3 motor single phase industrial vacuum cleaner for hazardous dust









Accessories		Ref. no.	Min. required	S3 L100 LC GV CC UKP	S3 L100 LC GV CC V110 UKP	S3 L50 LC
	CURVED BRUSH FOR PIPES D50/100 FE COMPL	Z7 22131	1	○	○	○
<b>Nozzle</b>						
	LIQ.SUCKER D50 MM400 INOX COMPLETE	Z7 22294	1	○	○	○
	LIQUIDS SUCKER D40 MM400 INOX COMPLETE	Z7 22296	1	○	○	○
	PACK10 RUBBERS FIX.NOZZLE MM600-700	Z8 20297	1	○	○	○
	PACK 10 STRIP MOBILE S. MM.400	Z8 23040	1	○	○	○
	PACK 10 STRIP MOBILE S. MM.500	Z8 23041	1	○	○	○
	PACK OF 10 RUBBERS 400 20086	Z8 20295	1	○	○	○

● Standard equipment, ○ Supplementary accessories, □ Mountable equipment













Accessories		Ref. no.	Min. required	S3 L100 LC FM	S3 L100 LC AU	S3 L100 LC AU UKP
<b>Filter</b>						
	ABSOLUTE FILTER KIT M.125/1216	Z5 60357	1	○	○	○
	KIT STAR FILTER D460 L CLASS	40000338	1	○	○	○
	SAFETY FILTER BAG 460MM STD W SAFETY BLT	4084001244	1	○	○	○
	STAR FILTER KIT D460 M CLASS	40000492	1	○	○	○
<b>Other</b>						
	BRACKET EMPTYING BELT D460 COMPLETE	Z5 36074	1	○	○	○
	EMPTYING BELT D460 COMPLETE	Z5 36073	1	○	○	○
	HARMONIC SPRINGPIN LINK	Z7 20328	1	○	○	○
	KIT MECANICAL FLOAT S3B SS	4056000519	1	○	○	○
	TRIM BASKET KIT D460 L100	40000915	1	○	○	○
<b>Bag</b>						
	5PCS PAPER BAGS GS82	81584000	1	○	○	○














## 3 motor single phase industrial vacuum cleaner for hazardous dust

Accessories		Ref. no.	Min. required	S3 L100 LC FM	S3 L100 LC AU	S3 L100 LC AU UKP
<b>Option</b>						
	EXTRACT CYCLONE D460 FE COMPLETE	Z5 60109	1	○	○	○
	KIT LIFTING MS2-S3	4056000493	1	○	○	○
	KIT LIQUIDS M.S3	4056000498	1	○	○	○
	KIT STAFFA SOLLEVAMENTO CONT. MODELLI CT	4056000394	1	○	○	○
<b>Vac Nozzle Fixed</b>						
	KIT FIX NOZZLE MM600 M.S2-S3	4056000487	1	○	○	○
<b>Assembly</b>						
	GRID AND VALVE D460 FE COMPLETE	Z5 60034	1	○	○	○
<b>Accessory Kit</b>						
	KIT AC.D50 EQUIPMENTS CLEANING	Z7 24156	1	○	○	○
	KIT AC.D50 INDUSTRIAL CLEANING	Z7 24151	1	○	○	○
	KIT ACC.D.50 GENERAL CLEANING	Z7 24146	1	○	○	○
	KIT INLET FOR PAPER BAG D70 SS WITH	Z5 60375	1	○	○	○
	KIT INLET X PAPER BAG D.70 COMP.WITH	Z5 60351	1	○	○	○
<b>Vacuum Hose and Connection</b>						
	BENT CONNECTION D40 FE	Z7 21013	1	○	○	○
	BENT CONNECTION D50 FE	Z7 21012	1	○	○	○
	BENT CONNECTION D50 INOX	Z7 21034	1	○	○	○
	BENT CONNECTION D50/40 Z.PLT.	Z7 22015	1	○	○	○
	BENT CONNECTION D70 FE	Z7 21032	1	○	○	○

## 3 motor single phase industrial vacuum cleaner for hazardous dust

Accessories	Ref. no.	Min. required	S3 L100 LC FM	S3 L100 LC AU	S3 L100 LC AU UKP
 CONNECTION JOINT D40 FE	Z7 21004	1	○	○	○
 CONNECTION JOINT D50 FE	Z7 21002	1	○	○	○
 CONNECTION JOINT D50 INOX	Z7 22241	1	○	○	○
 CONNECTION JOINT D70 FE	Z7 21000	1	○	○	○
 CONNECTION JOINT D70 INOX	Z7 22242	1	○	○	○
 CONNECTION TUBE D70 INOX	Z7 22231	0	○	○	○
 CONNECTION TUBE D70 STEEL	Z7 21001	1	○	○	○
 QUICK COUPLING D40 FE COMPLETE	Z7 22186	1	○	○	○
 QUICK COUPLING D50 FE COMPLETE	Z7 22187	1	○	○	○
 REDUCER D70/40 FE	Z7 22002	1	○	○	○
 REDUCER IRON D70/50	Z7 22001	1	○	○	○
 REDUCER REGULATION D70/50 COMPLETE	Z7 22162	1	○	○	○












## 3 motor single phase industrial vacuum cleaner for hazardous dust

Accessories		Ref. no.	Min. required	S3 L100 LC FM	S3 L100 LC AU	S3 L100 LC AU UKP
	REDUCER REGULATION D.70/40 COMPLETE	Z7 22164	1	○	○	○
<b>Cone Nozzle</b>						
	CONIC END D40/50/20 COMPLETE	Z7 22142	1	○	○	○
	CONIC END D50/20 COMPLETE	Z7 22141	1	○	○	○
	CONIC TUBE D40 RUBBER	Z7 21011	1	○	○	○
	CONIC TUBE D50 RUBBER	Z7 21010	1	○	○	○
	CONIC TUBE D70 RUBBER	Z7 21009	1	○	○	○
<b>Crevice Nozzle</b>						
	CURVED FLAT LANCE D50 FE	Z7 21075	1	○	○	○
	CURVED FLAT LANCE D70 MM1000 PVC	Z7 24012	1	○	○	○
	FLAT LANCE D40 MM500 PVC	Z7 24014	1	○	○	○
	FLAT LANCE D40 ZINC PLT.	Z7 21027	1	○	○	○
	FLAT LANCE D50 MM500 PVC	Z7 24013	1	○	○	○













## 3 motor single phase industrial vacuum cleaner for hazardous dust

Accessories	Ref. no.	Min. required	S3 L100 LC FM	S3 L100 LC AU	S3 L100 LC AU UKP
 FLAT LANCE D50 ZINC PLT.	Z7 21026	1	○	○	○
 FLAT LANCE D50/40 ZINC PLT.	Z7 22021	1	○	○	○
 FLAT LANCE D70 ZINC PLT.	Z7 21028	1	○	○	○
 FLAT LANCE DIAL D40 FE COMP.DIAL NYLON	Z7 22088	1	○	○	○
 FLAT LANCE DIAL D40 FE COMPLETE DIAL	Z7 22024	1	○	○	○
 FLAT LANCE DIAL D50 FE COMP.DIAL NYLON	Z7 22089	1	○	○	○
 FLAT LANCE DIAL D50 FE COMPLETE DIAL	Z7 22023	1	○	○	○
 GREY NBR NOZZLE D50 120MM	Z7 21030	1	○	○	○
 SCRAPING SUCKER D40 FE	Z7 22033	1	○	○	○
 SCRAPING SUCKER D40 INOX	Z7 22277	1	○	○	○
 SCRAPING SUCKER D50 FE	Z7 22034	1	○	○	○
 SCRAPING SUCKER D50 INOX	Z7 22278	1	○	○	○













## 3 motor single phase industrial vacuum cleaner for hazardous dust

Accessories		Ref. no.	Min. required	S3 L100 LC FM	S3 L100 LC AU	S3 L100 LC AU UKP
	SCRAPING SUCKER D70 MM 200	Z7 22090	1	○	○	○
<b>Hose and Connection</b>						
	BENT CONNECTION D40 INOX	Z7 21033	1	○	○	○
	CONNECTION JOINT D40 INOX	Z7 22240	1	○	○	○
	G.REDUCER D70/40 INOX COMPLETE	Z7 22235	0	○	○	○
	REDUCER D70/40 INOX	Z7 22224	1	○	○	○
	REDUCER D70/50 INOX	Z7 22225	1	○	○	○
	REG.REDUCER D70/50 INOX COMPLETE	Z7 22236	0	○	○	○
	TIE D40-60	Z8 40040	1	○	○	○
<b>Extension Tube</b>						
	ALUMINIUM EXTENSION D50 MT1 INLET PIN	Z7 22385	1	○	○	○
	EXTENSION D40 MT.1 ALUMINIUM COMPLETE	Z7 22008	1	○	○	○
	EXTENSION D40 MT.2 ALUMINIUM COMPLETE	Z7 22007	1	○	○	○

## 3 motor single phase industrial vacuum cleaner for hazardous dust

Accessories		Ref. no.	Min. required	S3 L100 LC FM	S3 L100 LC AU	S3 L100 LC AU UKP
	EXTENSION D40 MT.3 ALUMINIUM COMPLETE	Z7 22006	1	○	○	○
	EXTENSION D50 MT.1 ALUMINIUM COMPLETE	Z7 22005	1	○	○	○
	EXTENSION D50 MT.2 ALUMINIUM COMPLETE	Z7 22004	1	○	○	○
	EXTENSION D50 MT.3 ALUMINIUM COMPLETE	Z7 22003	1	○	○	○
	HANDGRIP D40 ALUMINIUM COMPLETE	Z7 22026	1	○	○	○
	HANDGRIP D40 CHROME PLT. COMPLETE	Z7 22121	1	○	○	○
	HANDGRIP D50 ALUMINIUM COMPLETE	Z7 22025	1	○	○	○
	HANDGRIP D50 CHROME PLT. COMPLETE	Z7 22122	1	○	○	○
<b>Vac Nozzle Wet</b>						
	LIQ.SUCKER D40 MM500 FE COMPLETE	Z7 22168	1	○	○	○
	LIQ.SUCKER D50 MM500 FE COMPLETE	Z7 22167	1	○	○	○
	LIQUIDS SUCKER D40 MM400 FE COMPLETE	Z7 22028	1	○	○	○
	LIQUIDS SUCKER D50 MM400 FE COMPLETE	Z7 22027	1	○	○	○

## 3 motor single phase industrial vacuum cleaner for hazardous dust

Accessories	Ref. no.	Min. required	S3 L100 LC FM	S3 L100 LC AU	S3 L100 LC AU UKP	
<b>Vac Nozzle Dry</b>						
	AUTOBUS SUCKER D50 200 AL. COMPLETE	Z7 22170	1	○	○	○
	BRUSH D40 MM220 30 COMPLETE	Z7 22193	1	○	○	○
	BRUSH D40 MM220 90 COMPLETE	Z7 22042	1	○	○	○
	BRUSH D40 MM300 30 COMPLETE	Z7 22194	1	○	○	○
	BRUSH D40 MM300 90 COMPLETE	Z7 22043	1	○	○	○
	BRUSH D40 MM400 30 COMPLETE	Z7 22195	1	○	○	○
	BRUSH D40 MM400 90 COMPLETE	Z7 22044	1	○	○	○
	BRUSH D50 MM220 30 COMPLETE	Z7 22196	1	○	○	○
	BRUSH D50 MM220 90 COMPLETE	Z7 22038	1	○	○	○
	BRUSH D50 MM300 30 COMPLETE	Z7 22197	1	○	○	○
	BRUSH D50 MM300 90 COMPLETE	Z7 22039	1	○	○	○
	BRUSH D50 MM400 30 COMPLETE	Z7 22198	1	○	○	○
















## 3 motor single phase industrial vacuum cleaner for hazardous dust

Accessories	Ref. no.	Min. required	S3 L100 LC FM	S3 L100 LC AU	S3 L100 LC AU UKP
 BRUSH D50 MM400 90 COMPLETE	Z7 22040	1	○	○	○
 MOB.SUCKER D50 MM500 FE COMPLETE	Z7 22147	1	○	○	○
 MOB.SUCKER STRIP D40 MM300 FE COMPLETE	Z7 22174	1	○	○	○
 MOB.SUCKER STRIP D40 MM400 FE COMPLETE	Z7 22138	1	○	○	○
 MOB.SUCKER STRIP D50 MM300 FE COMPLETE	Z7 22175	1	○	○	○
 MOB.SUCKER STRIP D50 MM400 FE COMPLETE	Z7 22137	1	○	○	○
 MOB.SUCKER STRIP D50 MM500 FE COMPLETE	Z7 22148	1	○	○	○
 MOBILE SUCKER D40 MM300 FE COMPLETE	Z7 22171	1	○	○	○
 MOBILE SUCKER D40 MM400 FE COMPLETE	Z7 22030	1	○	○	○
 MOBILE SUCKER D50 MM300 FE COMPLETE	Z7 22172	1	○	○	○
 MOBILE SUCKER D50 MM400 FE COMPLETE	Z7 22029	1	○	○	○
 SUCKER D40 MM400 ALUMINIUM	Z7 22031	1	○	○	○



## 3 motor single phase industrial vacuum cleaner for hazardous dust

Accessories		Ref. no.	Min. required	S3 L100 LC FM	S3 L100 LC AU	S3 L100 LC AU UKP
	SUCKER D50 MM400 ALUMINIUM	Z7 22032	1	○	○	○
	SUCKER X FURNACES D40 MM400 FE COMPLETE	Z7 22272	1	○	○	○
	SUCKER X FURNACES D50 MM400 FE COMPLETE	Z7 22273	1	○	○	○
<b>Round Brush Nozzle</b>						
	PAINTBRUSH D50/100 BRISTLES COMPLETE	Z7 22047	1	○	○	○
	PAINTBRUSH D50/100 STEEL COMPLETE	Z7 22048	1	○	○	○
<b>Hose Vacuum Cleaner</b>						
	AIR HOSE D40MT3+SLEEVES	Z7 22049	1	○	○	○
	AIR HOSE D40MT5+SLEEVES	Z7 22362	1	○	○	○
	AIR HOSE D50MT3+SLEEVES	Z7 22062	1	○	○	○
	AIR HOSE D50MT5+SLEEVES	Z7 22363	1	○	○	○
	AIR HOSE D70MT3+SLEEVES	Z7 22063	1	○	○	○
	AIR HOSE D70MT5+SLEEVES	Z7 22364	1	○	○	○



## 3 motor single phase industrial vacuum cleaner for hazardous dust

Accessories		Ref. no.	Min. required	S3 L100 LC FM	S3 L100 LC AU	S3 L100 LC AU UKP
	FLEX HOSE D40MT3+SLEEVES	Z7 22150	1	○	○	○
	FLEX HOSE D40MT5+SLEEVES	Z7 22360	1	○	○	○
	FLEX HOSE D50MT3+SLEEVES	Z7 22151	1	○	○	○
	FLEX HOSE D50MT5+SLEEVES	Z7 22361	1	○	○	○
	POLYURETHANE HOSE D40 3M +SLEEVES	Z7 22297	1	○	○	○
	POLYURETHANE HOSE D40 5M +SLEEVES	Z7 22365	1	○	○	○
	POLYURETHANE HOSE D50 3M +SLEEVES	Z7 22298	1	○	○	○
	POLYURETHANE HOSE D50 5M +SLEEVES	Z7 22366	1	○	○	○
	POLYURETHANE HOSE D70 3M +SLEEVES	Z7 22299	1	○	○	○
	POLYURETHANE HOSE D70 5M +SLEEVES	Z7 22367	1	○	○	○
<b>Pipe Cleaner Nozzle</b>						
	CURVED BRUSH FOR PIPES D40/100 FE COMPL	Z7 22132	1	○	○	○
	CURVED BRUSH FOR PIPES D50/100 FE COMPL	Z7 22131	1	○	○	○

## 3 motor single phase industrial vacuum cleaner for hazardous dust















Accessories		Ref. no.	Min. required	S3 L100 LC FM	S3 L100 LC AU	S3 L100 LC AU UKP
<b>Nozzle</b>						
	LIQ.SUCKER D50 MM400 INOX COMPLETE	Z7 22294	1	○	○	○
	LIQUIDS SUCKER D40 MM400 INOX COMPLETE	Z7 22296	1	○	○	○
	PACK10 RUBBERS FIX.NOZZLE MM600-700	Z8 20297	1	○	○	○
	PACK 10 STRIP MOBILE S. MM.400	Z8 23040	1	○	○	○
	PACK 10 STRIP MOBILE S. MM.500	Z8 23041	1	○	○	○
	PACK OF 10 RUBBERS 400 20086	Z8 20295	1	○	○	○

● Standard equipment, ○ Supplementary accessories, □ Mountable equipment













Accessories		Ref. no.	Min. required	S3 L100 LC AU V110 UKP	S3 L50 LC AU	S3 L50 LC V110 UKP
<b>Filter</b>						
	ABSOLUTE FILTER KIT M.125/1216	Z5 60357	1	○	○	○
	KIT STAR FILTER D460 L CLASS	40000338	1	○	○	○
	SAFETY FILTER BAG 460MM STD W SAFETY BLT	4084001244	1	○	○	○
	STAR FILTER KIT D460 M CLASS	40000492	1	○	○	○
<b>Other</b>						
	BRACKET EMPTYING BELT D460 COMPLETE	Z5 36074	1	○	○	○
	EMPTYING BELT D460 COMPLETE	Z5 36073	1	○	○	○
	HARMONIC SPRINGPIN LINK	Z7 20328	1	○	○	○
	KIT MECANICAL FLOAT S3B SS	4056000519	1	○	○	○
	TRIM BASKET KIT D460 L100	40000915	1	○	○	○
<b>Bag</b>						
	5PCS PAPER BAGS GS82	81584000	1	○	○	○
<b>Option</b>						
	EXTRACT CYCLONE D460 FE COMPLETE	Z5 60109	1	○	○	○
	KIT LIFTING MS2-S3	4056000493	1	○	○	○
	KIT LIQUIDS M.S3	4056000498	1	○	○	○












## 3 motor single phase industrial vacuum cleaner for hazardous dust

Accessories		Ref. no.	Min. required	S3 L100 LC AU V110 UKP	S3 L50 LC AU	S3 L50 LC V110 UKP
	KIT STAFFA SOLLEVAMENTO CONT. MODELLI CT	4056000394	1	○	○	○
<b>Vac Nozzle Fixed</b>						
	KIT FIX NOZZLE MM600 M.S2-S3	4056000487	1	○	○	○
<b>Assembly</b>						
	GRID AND VALVE D460 FE COMPLETE	Z5 60034	1	○	○	○
<b>Accessory Kit</b>						
	KIT AC.D50 EQUIPMENTS CLEANING	Z7 24156	1	○	○	○
	KIT AC.D50 INDUSTRIAL CLEANING	Z7 24151	1	○	○	○
	KIT ACC.D.50 GENERAL CLEANING	Z7 24146	1	○	○	○
	KIT INLET FOR PAPER BAG D70 SS WITH	Z5 60375	1	○	○	○
	KIT INLET X PAPER BAG D.70 COMP.WITH	Z5 60351	1	○	○	○
<b>Vacuum Hose and Connection</b>						
	BENT CONNECTION D40 FE	Z7 21013	1	○	○	○
	BENT CONNECTION D50 FE	Z7 21012	1	○	○	○
	BENT CONNECTION D50 INOX	Z7 21034	1	○	○	○
	BENT CONNECTION D50/40 Z.PLT.	Z7 22015	1	○	○	○
	BENT CONNECTION D70 FE	Z7 21032	1	○	○	○
	CONNECTION JOINT D40 FE	Z7 21004	1	○	○	○

## 3 motor single phase industrial vacuum cleaner for hazardous dust

Accessories		Ref. no.	Min. required	S3 L100 LC AU V110 UKP	S3 L50 LC AU	S3 L50 LC V110 UKP
	CONNECTION JOINT D50 FE	Z7 21002	1	○	○	○
	CONNECTION JOINT D50 INOX	Z7 22241	1	○	○	○
	CONNECTION JOINT D70 FE	Z7 21000	1	○	○	○
	CONNECTION JOINT D70 INOX	Z7 22242	1	○	○	○
	CONNECTION TUBE D70 INOX	Z7 22231	0	○	○	○
	CONNECTION TUBE D70 STEEL	Z7 21001	1	○	○	○
	QUICK COUPLING D40 FE COMPLETE	Z7 22186	1	○	○	○
	QUICK COUPLING D50 FE COMPLETE	Z7 22187	1	○	○	○
	REDUCER D70/40 FE	Z7 22002	1	○	○	○
	REDUCER IRON D70/50	Z7 22001	1	○	○	○
	REDUCER REGULATION D70/50 COMPLETE	Z7 22162	1	○	○	○
	REDUCER REGULATION D.70/40 COMPLETE	Z7 22164	1	○	○	○
<b>Cone Nozzle</b>						

## 3 motor single phase industrial vacuum cleaner for hazardous dust

Accessories		Ref. no.	Min. required	S3 L100 LC AU V110 UKP	S3 L50 LC AU	S3 L50 LC V110 UKP
	CONIC END D40/50/20 COMPLETE	Z7 22142	1	○	○	○
	CONIC END D50/20 COMPLETE	Z7 22141	1	○	○	○
	CONIC TUBE D40 RUBBER	Z7 21011	1	○	○	○
	CONIC TUBE D50 RUBBER	Z7 21010	1	○	○	○
	CONIC TUBE D70 RUBBER	Z7 21009	1	○	○	○
<b>Crevice Nozzle</b>						
	CURVED FLAT LANCE D50 FE	Z7 21075	1	○	○	○
	CURVED FLAT LANCE D70 MM1000 PVC	Z7 24012	1	○	○	○
	FLAT LANCE D40 MM500 PVC	Z7 24014	1	○	○	○
	FLAT LANCE D40 ZINC PLT.	Z7 21027	1	○	○	○
	FLAT LANCE D50 MM500 PVC	Z7 24013	1	○	○	○
	FLAT LANCE D50 ZINC PLT.	Z7 21026	1	○	○	○
	FLAT LANCE D50/40 ZINC PLT.	Z7 22021	1	○	○	○













## 3 motor single phase industrial vacuum cleaner for hazardous dust

Accessories		Ref. no.	Min. required	S3 L100 LC AU V110 UKP	S3 L50 LC AU	S3 L50 LC V110 UKP
	FLAT LANCE D70 ZINC PLT.	Z7 21028	1	○	○	○
	FLAT LANCE DIAL D40 FE COMP.DIAL NYLON	Z7 22088	1	○	○	○
	FLAT LANCE DIAL D40 FE COMPLETE DIAL	Z7 22024	1	○	○	○
	FLAT LANCE DIAL D50 FE COMP.DIAL NYLON	Z7 22089	1	○	○	○
	FLAT LANCE DIAL D50 FE COMPLETE DIAL	Z7 22023	1	○	○	○
	GREY NBR NOZZLE D50 120MM	Z7 21030	1	○	○	○
	SCRAPING SUCKER D40 FE	Z7 22033	1	○	○	○
	SCRAPING SUCKER D40 INOX	Z7 22277	1	○	○	○
	SCRAPING SUCKER D50 FE	Z7 22034	1	○	○	○
	SCRAPING SUCKER D50 INOX	Z7 22278	1	○	○	○
	SCRAPING SUCKER D70 MM 200	Z7 22090	1	○	○	○
<b>Hose and Connection</b>						
	BENT CONNECTION D40 INOX	Z7 21033	1	○	○	○











## 3 motor single phase industrial vacuum cleaner for hazardous dust

Accessories		Ref. no.	Min. required	S3 L100 LC AU V110 UKP	S3 L50 LC AU	S3 L50 LC V110 UKP
	CONNECTION JOINT D40 INOX	Z7 22240	1	○	○	○
	G.REDUCER D70/40 INOX COMPLETE	Z7 22235	0	○	○	○
	REDUCER D70/40 INOX	Z7 22224	1	○	○	○
	REDUCER D70/50 INOX	Z7 22225	1	○	○	○
	REG.REDUCER D70/50 INOX COMPLETE	Z7 22236	0	○	○	○
	TIE D40-60	Z8 40040	1	○	○	○
<b>Extension Tube</b>						
	ALUMINIUM EXTENSION D50 MT1 INLET PIN	Z7 22385	1	○	○	○
	EXTENSION D40 MT.1 ALUMINIUM COMPLETE	Z7 22008	1	○	○	○
	EXTENSION D40 MT.2 ALUMINIUM COMPLETE	Z7 22007	1	○	○	○
	EXTENSION D40 MT.3 ALUMINIUM COMPLETE	Z7 22006	1	○	○	○
	EXTENSION D50 MT.1 ALUMINIUM COMPLETE	Z7 22005	1	○	○	○
	EXTENSION D50 MT.2 ALUMINIUM COMPLETE	Z7 22004	1	○	○	○













## 3 motor single phase industrial vacuum cleaner for hazardous dust

Accessories		Ref. no.	Min. required	S3 L100 LC AU V110 UKP	S3 L50 LC AU	S3 L50 LC V110 UKP
	EXTENSION D50 MT.3 ALUMINIUM COMPLETE	Z7 22003	1	○	○	○
	HANDGRIP D40 ALUMINIUM COMPLETE	Z7 22026	1	○	○	○
	HANDGRIP D40 CHROME PLT. COMPLETE	Z7 22121	1	○	○	○
	HANDGRIP D50 ALUMINIUM COMPLETE	Z7 22025	1	○	○	○
	HANDGRIP D50 CHROME PLT. COMPLETE	Z7 22122	1	○	○	○
<b>Vac Nozzle Wet</b>						
	LIQ.SUCKER D40 MM500 FE COMPLETE	Z7 22168	1	○	○	○
	LIQ.SUCKER D50 MM500 FE COMPLETE	Z7 22167	1	○	○	○
	LIQUIDS SUCKER D40 MM400 FE COMPLETE	Z7 22028	1	○	○	○
	LIQUIDS SUCKER D50 MM400 FE COMPLETE	Z7 22027	1	○	○	○
<b>Vac Nozzle Dry</b>						
	AUTOBUS SUCKER D50 200 AL. COMPLETE	Z7 22170	1	○	○	○
	BRUSH D40 MM220 30 COMPLETE	Z7 22193	1	○	○	○

## 3 motor single phase industrial vacuum cleaner for hazardous dust

Accessories	Ref. no.	Min. required	S3 L100 LC AU V110 UKP	S3 L50 LC AU	S3 L50 LC V110 UKP
 BRUSH D40 MM220 90 COMPLETE	Z7 22042	1	○	○	○
 BRUSH D40 MM300 30 COMPLETE	Z7 22194	1	○	○	○
 BRUSH D40 MM300 90 COMPLETE	Z7 22043	1	○	○	○
 BRUSH D40 MM400 30 COMPLETE	Z7 22195	1	○	○	○
 BRUSH D40 MM400 90 COMPLETE	Z7 22044	1	○	○	○
 BRUSH D50 MM220 30 COMPLETE	Z7 22196	1	○	○	○
 BRUSH D50 MM220 90 COMPLETE	Z7 22038	1	○	○	○
 BRUSH D50 MM300 30 COMPLETE	Z7 22197	1	○	○	○
 BRUSH D50 MM300 90 COMPLETE	Z7 22039	1	○	○	○
 BRUSH D50 MM400 30 COMPLETE	Z7 22198	1	○	○	○
 BRUSH D50 MM400 90 COMPLETE	Z7 22040	1	○	○	○
 MOB.SUCKER D50 MM500 FE COMPLETE	Z7 22147	1	○	○	○












## 3 motor single phase industrial vacuum cleaner for hazardous dust

Accessories	Ref. no.	Min. required	S3 L100 LC AU V110 UKP	S3 L50 LC AU	S3 L50 LC V110 UKP
 MOB.SUCKER STRIP D40 MM300 FE COMPLETE	Z7 22174	1	○	○	○
 MOB.SUCKER STRIP D40 MM400 FE COMPLETE	Z7 22138	1	○	○	○
 MOB.SUCKER STRIP D50 MM300 FE COMPLETE	Z7 22175	1	○	○	○
 MOB.SUCKER STRIP D50 MM400 FE COMPLETE	Z7 22137	1	○	○	○
 MOB.SUCKER STRIP D50 MM500 FE COMPLETE	Z7 22148	1	○	○	○
 MOBILE SUCKER D40 MM300 FE COMPLETE	Z7 22171	1	○	○	○
 MOBILE SUCKER D40 MM400 FE COMPLETE	Z7 22030	1	○	○	○
 MOBILE SUCKER D50 MM300 FE COMPLETE	Z7 22172	1	○	○	○
 MOBILE SUCKER D50 MM400 FE COMPLETE	Z7 22029	1	○	○	○
 SUCKER D40 MM400 ALUMINIUM	Z7 22031	1	○	○	○
 SUCKER D50 MM400 ALUMINIUM	Z7 22032	1	○	○	○
 SUCKER X FURNACES D40 MM400 FE COMPLETE	Z7 22272	1	○	○	○



## 3 motor single phase industrial vacuum cleaner for hazardous dust

Accessories		Ref. no.	Min. required	S3 L100 LC AU V110 UKP	S3 L50 LC AU	S3 L50 LC V110 UKP
	SUCKER X FURNACES D50 MM400 FE COMPLETE	Z7 22273	1	○	○	○
<b>Round Brush Nozzle</b>						
	PAINTBRUSH D50/100 BRISTLES COMPLETE	Z7 22047	1	○	○	○
	PAINTBRUSH D50/100 STEEL COMPLETE	Z7 22048	1	○	○	○
<b>Hose Vacuum Cleaner</b>						
	AIR HOSE D40MT3+SLEEVES	Z7 22049	1	○	○	○
	AIR HOSE D40MT5+SLEEVES	Z7 22362	1	○	○	○
	AIR HOSE D50MT3+SLEEVES	Z7 22062	1	○	○	○
	AIR HOSE D50MT5+SLEEVES	Z7 22363	1	○	○	○
	AIR HOSE D70MT3+SLEEVES	Z7 22063	1	○	○	○
	AIR HOSE D70MT5+SLEEVES	Z7 22364	1	○	○	○
	FLEX HOSE D40MT3+SLEEVES	Z7 22150	1	○	○	○
	FLEX HOSE D40MT5+SLEEVES	Z7 22360	1	○	○	○



## 3 motor single phase industrial vacuum cleaner for hazardous dust

Accessories		Ref. no.	Min. required	S3 L100 LC AU V110 UKP	S3 L50 LC AU	S3 L50 LC V110 UKP
	FLEX HOSE D50MT3+SLEEVES	Z7 22151	1	○	○	○
	FLEX HOSE D50MT5+SLEEVES	Z7 22361	1	○	○	○
	POLYURETHANE HOSE D40 3M +SLEEVES	Z7 22297	1	○	○	○
	POLYURETHANE HOSE D40 5M +SLEEVES	Z7 22365	1	○	○	○
	POLYURETHANE HOSE D50 3M +SLEEVES	Z7 22298	1	○	○	○
	POLYURETHANE HOSE D50 5M +SLEEVES	Z7 22366	1	○	○	○
	POLYURETHANE HOSE D70 3M +SLEEVES	Z7 22299	1	○	○	○
	POLYURETHANE HOSE D70 5M +SLEEVES	Z7 22367	1	○	○	○
<b>Pipe Cleaner Nozzle</b>						
	CURVED BRUSH FOR PIPES D40/100 FE COMPL	Z7 22132	1	○	○	○
	CURVED BRUSH FOR PIPES D50/100 FE COMPL	Z7 22131	1	○	○	○
<b>Nozzle</b>						
	LIQ.SUCKER D50 MM400 INOX COMPLETE	Z7 22294	1	○	○	○

## 3 motor single phase industrial vacuum cleaner for hazardous dust











Accessories		Ref. no.	Min. required	S3 L100 LC AU V110 UKP	S3 L50 LC AU	S3 L50 LC V110 UKP
	LIQUIDS SUCKER D40 MM400 INOX COMPLETE	Z7 22296	1	○	○	○
	PACK10 RUBBERS FIX.NOZZLE MM600-700	Z8 20297	1	○	○	○
	PACK 10 STRIP MOBILE S. MM.400	Z8 23040	1	○	○	○
	PACK 10 STRIP MOBILE S. MM.500	Z8 23041	1	○	○	○
	PACK OF 10 RUBBERS 400 20086	Z8 20295	1	○	○	○

● Standard equipment, ○ Supplementary accessories, □ Mountable equipment

Accessories		Ref. no.	Min. required	S3 L100 LC L GV CC	S3 L100 LC L GV CC UKP	S3 L100 LC L GV CC 2X
<b>Filter</b>						
	ABSOLUTE FILTER KIT M.125/1216	Z5 60357	1	○	○	○
	KIT STAR FILTER D460 L CLASS	40000338	1	○	○	○
	SAFETY FILTER BAG 460MM STD W SAFETY BLT	4084001244	1	○	○	○
	STAR FILTER KIT D460 M CLASS	40000492	1	○	○	○
<b>Other</b>						
	BRACKET EMPTYING BELT D460 COMPLETE	Z5 36074	1	○	○	○
	EMPTYING BELT D460 COMPLETE	Z5 36073	1	○	○	○
	HARMONIC SPRINGPIN LINK	Z7 20328	1	○	○	○
	KIT MECANICAL FLOAT S3B SS	4056000519	1	○	○	○
	TRIM BASKET KIT D460 L100	40000915	1	○	○	○
<b>Bag</b>						
	5PCS PAPER BAGS GS82	81584000	1	○	○	○
<b>Option</b>						
	EXTRACT CYCLONE D460 FE COMPLETE	Z5 60109	1	○	○	○
	KIT LIFTING MS2-S3	4056000493	1	○	○	○
	KIT LIQUIDS M.S3	4056000498	1	○	○	○
	KIT STAFFA SOLLEVAMENTO CONT. MODELLI CT	4056000394	1	○	○	○
<b>Vac Nozzle Fixed</b>						















## 3 motor single phase industrial vacuum cleaner for hazardous dust













Accessories		Ref. no.	Min. required	S3 L100 LC L GV CC	S3 L100 LC L GV CC UKP	S3 L100 LC L GV CC 2X
	KIT FIX NOZZLE MM600 M.S2-S3	4056000487	1	○	○	○
<b>Assembly</b>						
	GRID AND VALVE D460 FE COMPLETE	Z5 60034	1	●	●	●
<b>Accessory Kit</b>						
	KIT AC.D50 EQUIPMENTS CLEANING	Z7 24156	1	○	○	○
	KIT AC.D50 INDUSTRIAL CLEANING	Z7 24151	1	○	○	○
	KIT ACC.D.50 GENERAL CLEANING	Z7 24146	1	○	○	○
	KIT INLET FOR PAPER BAG D70 SS WITH	Z5 60375	1	○	○	○
	KIT INLET X PAPER BAG D.70 COMP.WITH	Z5 60351	1	○	○	○
<b>Vacuum Hose and Connection</b>						
	BENT CONNECTION D40 FE	Z7 21013	1	○	○	○
	BENT CONNECTION D50 FE	Z7 21012	1	○	○	○
	BENT CONNECTION D50 INOX	Z7 21034	1	○	○	○
	BENT CONNECTION D50/40 Z.PLT.	Z7 22015	1	○	○	○
	BENT CONNECTION D70 FE	Z7 21032	1	○	○	○
	CONNECTION JOINT D40 FE	Z7 21004	1	○	○	○
	CONNECTION JOINT D50 FE	Z7 21002	1	○	○	○



## 3 motor single phase industrial vacuum cleaner for hazardous dust

Accessories		Ref. no.	Min. required	S3 L100 LC L GV CC	S3 L100 LC L GV CC UKP	S3 L100 LC L GV CC 2X
	CONNECTION JOINT D50 INOX	Z7 22241	1	○	○	○
	CONNECTION JOINT D70 FE	Z7 21000	1	○	○	○
	CONNECTION JOINT D70 INOX	Z7 22242	1	○	○	○
	CONNECTION TUBE D70 INOX	Z7 22231	0	○	○	○
	CONNECTION TUBE D70 STEEL	Z7 21001	1	○	○	○
	QUICK COUPLING D40 FE COMPLETE	Z7 22186	1	○	○	○
	QUICK COUPLING D50 FE COMPLETE	Z7 22187	1	○	○	○
	REDUCER D70/40 FE	Z7 22002	1	○	○	○
	REDUCER IRON D70/50	Z7 22001	1	○	○	○
	REDUCER REGULATION D70/50 COMPLETE	Z7 22162	1	○	○	○
	REDUCER REGULATION D.70/40 COMPLETE	Z7 22164	1	○	○	○
<b>Cone Nozzle</b>						
	CONIC END D40/50/20 COMPLETE	Z7 22142	1	○	○	○













## 3 motor single phase industrial vacuum cleaner for hazardous dust

Accessories		Ref. no.	Min. required	S3 L100 LC L GV CC	S3 L100 LC L GV CC UKP	S3 L100 LC L GV CC 2X
	CONIC END D50/20 COMPLETE	Z7 22141	1	○	○	○
	CONIC TUBE D40 RUBBER	Z7 21011	1	○	○	○
	CONIC TUBE D50 RUBBER	Z7 21010	1	○	○	○
	CONIC TUBE D70 RUBBER	Z7 21009	1	○	○	○
<b>Crevice Nozzle</b>						
	CURVED FLAT LANCE D50 FE	Z7 21075	1	○	○	○
	CURVED FLAT LANCE D70 MM1000 PVC	Z7 24012	1	○	○	○
	FLAT LANCE D40 MM500 PVC	Z7 24014	1	○	○	○
	FLAT LANCE D40 ZINC PLT.	Z7 21027	1	○	○	○
	FLAT LANCE D50 MM500 PVC	Z7 24013	1	○	○	○
	FLAT LANCE D50 ZINC PLT.	Z7 21026	1	○	○	○
	FLAT LANCE D50/40 ZINC PLT.	Z7 22021	1	○	○	○
	FLAT LANCE D70 ZINC PLT.	Z7 21028	1	○	○	○

## 3 motor single phase industrial vacuum cleaner for hazardous dust












Accessories		Ref. no.	Min. required	S3 L100 LC L GV CC	S3 L100 LC L GV CC UKP	S3 L100 LC L GV CC 2X
	FLAT LANCE DIAL D40 FE COMP.DIAL NYLON	Z7 22088	1	○	○	○
	FLAT LANCE DIAL D40 FE COMPLETE DIAL	Z7 22024	1	○	○	○
	FLAT LANCE DIAL D50 FE COMP.DIAL NYLON	Z7 22089	1	○	○	○
	FLAT LANCE DIAL D50 FE COMPLETE DIAL	Z7 22023	1	○	○	○
	GREY NBR NOZZLE D50 120MM	Z7 21030	1	○	○	○
	SCRAPING SUCKER D40 FE	Z7 22033	1	○	○	○
	SCRAPING SUCKER D40 INOX	Z7 22277	1	○	○	○
	SCRAPING SUCKER D50 FE	Z7 22034	1	○	○	○
	SCRAPING SUCKER D50 INOX	Z7 22278	1	○	○	○
	SCRAPING SUCKER D70 MM 200	Z7 22090	1	○	○	○
<b>Hose and Connection</b>						
	BENT CONNECTION D40 INOX	Z7 21033	1	○	○	○
	CONNECTION JOINT D40 INOX	Z7 22240	1	○	○	○

## 3 motor single phase industrial vacuum cleaner for hazardous dust

Accessories		Ref. no.	Min. required	S3 L100 LC L GV CC	S3 L100 LC L GV CC UKP	S3 L100 LC L GV CC 2X
	G.REDUCER D70/40 INOX COMPLETE	Z7 22235	0	○	○	○
	REDUCER D70/40 INOX	Z7 22224	1	○	○	○
	REDUCER D70/50 INOX	Z7 22225	1	○	○	○
	REG.REDUCER D70/50 INOX COMPLETE	Z7 22236	0	○	○	○
	TIE D40-60	Z8 40040	1	○	○	○
<b>Extension Tube</b>						
	ALUMINIUM EXTENSION D50 MT1 INLET PIN	Z7 22385	1	○	○	○
	EXTENSION D40 MT.1 ALUMINIUM COMPLETE	Z7 22008	1	○	○	○
	EXTENSION D40 MT.2 ALUMINIUM COMPLETE	Z7 22007	1	○	○	○
	EXTENSION D40 MT.3 ALUMINIUM COMPLETE	Z7 22006	1	○	○	○
	EXTENSION D50 MT.1 ALUMINIUM COMPLETE	Z7 22005	1	○	○	○
	EXTENSION D50 MT.2 ALUMINIUM COMPLETE	Z7 22004	1	○	○	○
	EXTENSION D50 MT.3 ALUMINIUM COMPLETE	Z7 22003	1	○	○	○















## 3 motor single phase industrial vacuum cleaner for hazardous dust

Accessories		Ref. no.	Min. required	S3 L100 LC L GV CC	S3 L100 LC L GV CC UKP	S3 L100 LC L GV CC 2X
	HANDGRIP D40 ALUMINIUM COMPLETE	Z7 22026	1	○	○	○
	HANDGRIP D40 CHROME PLT. COMPLETE	Z7 22121	1	○	○	○
	HANDGRIP D50 ALUMINIUM COMPLETE	Z7 22025	1	○	○	○
	HANDGRIP D50 CHROME PLT. COMPLETE	Z7 22122	1	○	○	○
<b>Vac Nozzle Wet</b>						
	LIQ.SUCKER D40 MM500 FE COMPLETE	Z7 22168	1	○	○	○
	LIQ.SUCKER D50 MM500 FE COMPLETE	Z7 22167	1	○	○	○
	LIQUIDS SUCKER D40 MM400 FE COMPLETE	Z7 22028	1	○	○	○
	LIQUIDS SUCKER D50 MM400 FE COMPLETE	Z7 22027	1	○	○	○
<b>Vac Nozzle Dry</b>						
	AUTOBUS SUCKER D50 200 AL. COMPLETE	Z7 22170	1	○	○	○
	BRUSH D40 MM220 30 COMPLETE	Z7 22193	1	○	○	○
	BRUSH D40 MM220 90 COMPLETE	Z7 22042	1	○	○	○

## 3 motor single phase industrial vacuum cleaner for hazardous dust

Accessories	Ref. no.	Min. required	S3 L100 LC L GV CC	S3 L100 LC L GV CC UKP	S3 L100 LC L GV CC 2X
 BRUSH D40 MM300 30 COMPLETE	Z7 22194	1	○	○	○
 BRUSH D40 MM300 90 COMPLETE	Z7 22043	1	○	○	○
 BRUSH D40 MM400 30 COMPLETE	Z7 22195	1	○	○	○
 BRUSH D40 MM400 90 COMPLETE	Z7 22044	1	○	○	○
 BRUSH D50 MM220 30 COMPLETE	Z7 22196	1	○	○	○
 BRUSH D50 MM220 90 COMPLETE	Z7 22038	1	○	○	○
 BRUSH D50 MM300 30 COMPLE	Z7 22197	1	○	○	○
 BRUSH D50 MM300 90 COMPLETE	Z7 22039	1	○	○	○
 BRUSH D50 MM400 30 COMPLETE	Z7 22198	1	○	○	○
 BRUSH D50 MM400 90 COMPLETE	Z7 22040	1	○	○	○
 MOB.SUCKER D50 MM500 FE COMPLETE	Z7 22147	1	○	○	○
 MOB.SUCKER STRIP D40 MM300 FE COMPLETE	Z7 22174	1	○	○	○

## 3 motor single phase industrial vacuum cleaner for hazardous dust

Accessories	Ref. no.	Min. required	S3 L100 LC L GV CC	S3 L100 LC L GV CC UKP	S3 L100 LC L GV CC 2X
 MOB.SUCKER STRIP D40 MM400 FE COMPLETE	Z7 22138	1	○	○	○
 MOB.SUCKER STRIP D50 MM300 FE COMPLETE	Z7 22175	1	○	○	○
 MOB.SUCKER STRIP D50 MM400 FE COMPLETE	Z7 22137	1	○	○	○
 MOB.SUCKER STRIP D50 MM500 FE COMPLETE	Z7 22148	1	○	○	○
 MOBILE SUCKER D40 MM300 FE COMPLETE	Z7 22171	1	○	○	○
 MOBILE SUCKER D40 MM400 FE COMPLETE	Z7 22030	1	○	○	○
 MOBILE SUCKER D50 MM300 FE COMPLETE	Z7 22172	1	○	○	○
 MOBILE SUCKER D50 MM400 FE COMPLETE	Z7 22029	1	○	○	○
 SUCKER D40 MM400 ALUMINIUM	Z7 22031	1	○	○	○
 SUCKER D50 MM400 ALUMINIUM	Z7 22032	1	○	○	○
 SUCKER X FURNACES D40 MM400 FE COMPLETE	Z7 22272	1	○	○	○
 SUCKER X FURNACES D50 MM400 FE COMPLETE	Z7 22273	1	○	○	○
<b>Round Brush Nozzle</b>					













## 3 motor single phase industrial vacuum cleaner for hazardous dust

Accessories		Ref. no.	Min. required	S3 L100 LC L GV CC	S3 L100 LC L GV CC UKP	S3 L100 LC L GV CC 2X
	PAINTBRUSH D50/100 BRISTLES COMPLETE	Z7 22047	1	○	○	○
	PAINTBRUSH D50/100 STEEL COMPLETE	Z7 22048	1	○	○	○
<b>Hose Vacuum Cleaner</b>						
	AIR HOSE D40MT3+SLEEVES	Z7 22049	1	○	○	○
	AIR HOSE D40MT5+SLEEVES	Z7 22362	1	○	○	○
	AIR HOSE D50MT3+SLEEVES	Z7 22062	1	○	○	○
	AIR HOSE D50MT5+SLEEVES	Z7 22363	1	○	○	○
	AIR HOSE D70MT3+SLEEVES	Z7 22063	1	○	○	○
	AIR HOSE D70MT5+SLEEVES	Z7 22364	1	○	○	○
	FLEX HOSE D40MT3+SLEEVES	Z7 22150	1	○	○	○
	FLEX HOSE D40MT5+SLEEVES	Z7 22360	1	○	○	○
	FLEX HOSE D50MT3+SLEEVES	Z7 22151	1	○	○	○
	FLEX HOSE D50MT5+SLEEVES	Z7 22361	1	○	○	○









## 3 motor single phase industrial vacuum cleaner for hazardous dust

Accessories		Ref. no.	Min. required	S3 L100 LC L GV CC	S3 L100 LC L GV CC UKP	S3 L100 LC L GV CC 2X
	POLYURETHANE HOSE D40 3M +SLEEVES	Z7 22297	1	○	○	○
	POLYURETHANE HOSE D40 5M +SLEEVES	Z7 22365	1	○	○	○
	POLYURETHANE HOSE D50 3M +SLEEVES	Z7 22298	1	○	○	○
	POLYURETHANE HOSE D50 5M +SLEEVES	Z7 22366	1	○	○	○
	POLYURETHANE HOSE D70 3M +SLEEVES	Z7 22299	1	○	○	○
	POLYURETHANE HOSE D70 5M +SLEEVES	Z7 22367	1	○	○	○
<b>Pipe Cleaner Nozzle</b>						
	CURVED BRUSH FOR PIPES D40/100 FE COMPL	Z7 22132	1	○	○	○
	CURVED BRUSH FOR PIPES D50/100 FE COMPL	Z7 22131	1	○	○	○
<b>Nozzle</b>						
	LIQ.SUCKER D50 MM400 INOX COMPLETE	Z7 22294	1	○	○	○
	LIQUIDS SUCKER D40 MM400 INOX COMPLETE	Z7 22296	1	○	○	○
	PACK10 RUBBERS FIX.NOZZLE MM600-700	Z8 20297	1	○	○	○
	PACK 10 STRIP MOBILE S. MM.400	Z8 23040	1	○	○	○
	PACK 10 STRIP MOBILE S. MM.500	Z8 23041	1	○	○	○

## 3 motor single phase industrial vacuum cleaner for hazardous dust












Accessories		Ref. no.	Min. required	S3 L100 LC L GV CC	S3 L100 LC L GV CC UKP	S3 L100 LC L GV CC 2X
	PACK OF 10 RUBBERS 400 20086	Z8 20295	1	○	○	○

● Standard equipment, ○ Supplementary accessories, □ Mountable equipment













Accessories		Ref. no.	Min. required	S3 L50 LC GV CC	S3 L50 LC L GV CC 3X	S3 L100 LC FM AU UKP
<b>Filter</b>						
	ABSOLUTE FILTER KIT M.125/1216	Z5 60357	1	○		○
	KIT STAR FILTER D460 L CLASS	40000338	1	○		○
	SAFETY FILTER BAG 460MM STD W SAFETY BLT	4084001244	1	○		○
	STAR FILTER KIT D460 M CLASS	40000492	1	○		○
<b>Other</b>						
	BRACKET EMPTYING BELT D460 COMPLETE	Z5 36074	1	○		○
	EMPTYING BELT D460 COMPLETE	Z5 36073	1	○		○
	HARMONIC SPRINGPIN LINK	Z7 20328	1	○		○
	KIT MECANICAL FLOAT S3B SS	4056000519	1	○		○
	TRIM BASKET KIT D460 L100	40000915	1	○		○
<b>Bag</b>						
	5PCS PAPER BAGS GS82	81584000	1	○		○
<b>Option</b>						
	EXTRACT CYCLONE D460 FE COMPLETE	Z5 60109	1	○		○
	KIT LIFTING MS2-S3	4056000493	1	○		○
	KIT LIQUIDS M.S3	4056000498	1	○		○
	KIT STAFFA SOLLEVAMENTO CONT. MODELLI CT	4056000394	1	○		○
<b>Vac Nozzle Fixed</b>						
	KIT FIX NOZZLE MM600 M.S2-S3	4056000487	1	○		○
<b>Assembly</b>						
	GRID AND VALVE D460 FE COMPLETE	Z5 60034	1	●	○	○
<b>Accessory Kit</b>						















## 3 motor single phase industrial vacuum cleaner for hazardous dust

Accessories		Ref. no.	Min. required	S3 L50 LC GV CC	S3 L50 LC L GV CC 3X	S3 L100 LC FM AU UKP
	KIT AC.D50 EQUIPMENTS CLEANING	Z7 24156	1	○		○
	KIT AC.D50 INDUSTRIAL CLEANING	Z7 24151	1	○		○
	KIT ACC.D.50 GENERAL CLEANING	Z7 24146	1	○		○
	KIT INLET FOR PAPER BAG D70 SS WITH	Z5 60375	1	○		○
	KIT INLET X PAPER BAG D.70 COMP.WITH	Z5 60351	1	○		○
<b>Vacuum Hose and Connection</b>						
	BENT CONNECTION D40 FE	Z7 21013	1	○		○
	BENT CONNECTION D50 FE	Z7 21012	1	○		○
	BENT CONNECTION D50 INOX	Z7 21034	1	○		○
	BENT CONNECTION D50/40 Z.PLT.	Z7 22015	1	○		○
	BENT CONNECTION D70 FE	Z7 21032	1	○		○
	CONNECTION JOINT D40 FE	Z7 21004	1	○		○
	CONNECTION JOINT D50 FE	Z7 21002	1	○		○
	CONNECTION JOINT D50 INOX	Z7 22241	1	○		○
	CONNECTION JOINT D70 FE	Z7 21000	1	○		○

## 3 motor single phase industrial vacuum cleaner for hazardous dust

Accessories		Ref. no.	Min. required	S3 L50 LC GV CC	S3 L50 LC L GV CC 3X	S3 L100 LC FM AU UKP
	CONNECTION JOINT D70 INOX	Z7 22242	1	○		○
	CONNECTION TUBE D70 INOX	Z7 22231	0	○		○
	CONNECTION TUBE D70 STEEL	Z7 21001	1	○		○
	QUICK COUPLING D40 FE COMPLETE	Z7 22186	1	○		○
	QUICK COUPLING D50 FE COMPLETE	Z7 22187	1	○		○
	REDUCER D70/40 FE	Z7 22002	1	○		○
	REDUCER IRON D70/50	Z7 22001	1	○	○	○
	REDUCER REGULATION D70/50 COMPLETE	Z7 22162	1	○		○
	REDUCER REGULATION D.70/40 COMPLETE	Z7 22164	1	○		○
<b>Cone Nozzle</b>						
	CONIC END D40/50/20 COMPLETE	Z7 22142	1	○		○
	CONIC END D50/20 COMPLETE	Z7 22141	1	○		○
	CONIC TUBE D40 RUBBER	Z7 21011	1	○		○













## 3 motor single phase industrial vacuum cleaner for hazardous dust

Accessories		Ref. no.	Min. required	S3 L50 LC GV CC	S3 L50 LC L GV CC 3X	S3 L100 LC FM AU UKP
	CONIC TUBE D50 RUBBER	Z7 21010	1	○	○	○
	CONIC TUBE D70 RUBBER	Z7 21009	1	○		○
<b>Crevice Nozzle</b>						
	CURVED FLAT LANCE D50 FE	Z7 21075	1	○		○
	CURVED FLAT LANCE D70 MM1000 PVC	Z7 24012	1	○		○
	FLAT LANCE D40 MM500 PVC	Z7 24014	1	○		○
	FLAT LANCE D40 ZINC PLT.	Z7 21027	1	○		○
	FLAT LANCE D50 MM500 PVC	Z7 24013	1	○		○
	FLAT LANCE D50 ZINC PLT.	Z7 21026	1	○	○	○
	FLAT LANCE D50/40 ZINC PLT.	Z7 22021	1	○		○
	FLAT LANCE D70 ZINC PLT.	Z7 21028	1	○		○
	FLAT LANCE DIAL D40 FE COMP. DIAL NYLON	Z7 22088	1	○		○
	FLAT LANCE DIAL D40 FE COMPLETE DIAL	Z7 22024	1	○		○












## 3 motor single phase industrial vacuum cleaner for hazardous dust

Accessories		Ref. no.	Min. required	S3 L50 LC GV CC	S3 L50 LC L GV CC 3X	S3 L100 LC FM AU UKP
	FLAT LANCE DIAL D50 FE COMP.DIAL NYLON	Z7 22089	1	○		○
	FLAT LANCE DIAL D50 FE COMPLETE DIAL	Z7 22023	1	○		○
	GREY NBR NOZZLE D50 120MM	Z7 21030	1	○		○
	SCRAPING SUCKER D40 FE	Z7 22033	1	○		○
	SCRAPING SUCKER D40 INOX	Z7 22277	1	○		○
	SCRAPING SUCKER D50 FE	Z7 22034	1	○		○
	SCRAPING SUCKER D50 INOX	Z7 22278	1	○		○
	SCRAPING SUCKER D70 MM 200	Z7 22090	1	○		○
<b>Hose and Connection</b>						
	BENT CONNECTION D40 INOX	Z7 21033	1	○		○
	CONNECTION JOINT D40 INOX	Z7 22240	1	○		○
	G.REDUCER D70/40 INOX COMPLETE	Z7 22235	0	○		○
	REDUCER D70/40 INOX	Z7 22224	1	○		○

## 3 motor single phase industrial vacuum cleaner for hazardous dust









Accessories		Ref. no.	Min. required	S3 L50 LC GV CC	S3 L50 LC L GV CC 3X	S3 L100 LC FM AU UKP
	REDUCER D70/50 INOX	Z7 22225	1	○		○
	REG.REDUCER D70/50 INOX COMPLETE	Z7 22236	0	○		○
	TIE D40-60	Z8 40040	1	○		○
<b>Extension Tube</b>						
	ALUMINIUM EXTENSION D50 MT1 INLET PIN	Z7 22385	1	○		○
	EXTENSION D40 MT.1 ALUMINIUM COMPLETE	Z7 22008	1	○		○
	EXTENSION D40 MT.2 ALUMINIUM COMPLETE	Z7 22007	1	○		○
	EXTENSION D40 MT.3 ALUMINIUM COMPLETE	Z7 22006	1	○		○
	EXTENSION D50 MT.1 ALUMINIUM COMPLETE	Z7 22005	1	○		○
	EXTENSION D50 MT.2 ALUMINIUM COMPLETE	Z7 22004	1	○		○
	EXTENSION D50 MT.3 ALUMINIUM COMPLETE	Z7 22003	1	○		○
	HANDGRIP D40 ALUMINIUM COMPLETE	Z7 22026	1	○		○
	HANDGRIP D40 CHROME PLT. COMPLETE	Z7 22121	1	○		○

## 3 motor single phase industrial vacuum cleaner for hazardous dust













Accessories		Ref. no.	Min. required	S3 L50 LC GV CC	S3 L50 LC L GV CC 3X	S3 L100 LC FM AU UKP
	HANDGRIP D50 ALUMINIUM COMPLETE	Z7 22025	1	○	○	○
	HANDGRIP D50 CHROME PLT. COMPLETE	Z7 22122	1	○		○
<b>Vac Nozzle Wet</b>						
	LIQ.SUCKER D40 MM500 FE COMPLETE	Z7 22168	1	○		○
	LIQ.SUCKER D50 MM500 FE COMPLETE	Z7 22167	1	○		○
	LIQUIDS SUCKER D40 MM400 FE COMPLETE	Z7 22028	1	○		○
	LIQUIDS SUCKER D50 MM400 FE COMPLETE	Z7 22027	1	○		○
<b>Vac Nozzle Dry</b>						
	AUTOBUS SUCKER D50 200 AL. COMPLETE	Z7 22170	1	○		○
	BRUSH D40 MM220 30 COMPLETE	Z7 22193	1	○		○
	BRUSH D40 MM220 90 COMPLETE	Z7 22042	1	○		○
	BRUSH D40 MM300 30 COMPLETE	Z7 22194	1	○		○
	BRUSH D40 MM300 90 COMPLETE	Z7 22043	1	○		○















## 3 motor single phase industrial vacuum cleaner for hazardous dust

Accessories	Ref. no.	Min. required	S3 L50 LC GV CC	S3 L50 LC L GV CC 3X	S3 L100 LC FM AU UKP
 BRUSH D40 MM400 30 COMPLETE	Z7 22195	1	○		○
 BRUSH D40 MM400 90 COMPLETE	Z7 22044	1	○		○
 BRUSH D50 MM220 30 COMPLETE	Z7 22196	1	○		○
 BRUSH D50 MM220 90 COMPLETE	Z7 22038	1	○		○
 BRUSH D50 MM300 30 COMPLE	Z7 22197	1	○		○
 BRUSH D50 MM300 90 COMPLETE	Z7 22039	1	○		○
 BRUSH D50 MM400 30 COMPLETE	Z7 22198	1	○		○
 BRUSH D50 MM400 90 COMPLETE	Z7 22040	1	○		○
 MOB.SUCKER D50 MM500 FE COMPLETE	Z7 22147	1	○		○
 MOB.SUCKER STRIP D40 MM300 FE COMPLETE	Z7 22174	1	○		○
 MOB.SUCKER STRIP D40 MM400 FE COMPLETE	Z7 22138	1	○		○
 MOB.SUCKER STRIP D50 MM300 FE COMPLETE	Z7 22175	1	○		○

## 3 motor single phase industrial vacuum cleaner for hazardous dust










Accessories	Ref. no.	Min. required	S3 L50 LC GV CC	S3 L50 LC L GV CC 3X	S3 L100 LC FM AU UKP
 MOB.SUCKER STRIP D50 MM400 FE COMPLETE	Z7 22137	1	○		○
 MOB.SUCKER STRIP D50 MM500 FE COMPLETE	Z7 22148	1	○		○
 MOBILE SUCKER D40 MM300 FE COMPLETE	Z7 22171	1	○		○
 MOBILE SUCKER D40 MM400 FE COMPLETE	Z7 22030	1	○		○
 MOBILE SUCKER D50 MM300 FE COMPLETE	Z7 22172	1	○	○	○
 MOBILE SUCKER D50 MM400 FE COMPLETE	Z7 22029	1	○		○
 SUCKER D40 MM400 ALUMINIUM	Z7 22031	1	○		○
 SUCKER D50 MM400 ALUMINIUM	Z7 22032	1	○		○
 SUCKER X FURNACES D40 MM400 FE COMPLETE	Z7 22272	1	○		○
 SUCKER X FURNACES D50 MM400 FE COMPLETE	Z7 22273	1	○		○
<b>Round Brush Nozzle</b>					
 PAINTBRUSH D50/100 BRISTLES COMPLETE	Z7 22047	1	○		○
 PAINTBRUSH D50/100 STEEL COMPLETE	Z7 22048	1	○		○

## 3 motor single phase industrial vacuum cleaner for hazardous dust

Accessories		Ref. no.	Min. required	S3 L50 LC GV CC	S3 L50 LC L GV CC 3X	S3 L100 LC FM AU UKP
<b>Hose Vacuum Cleaner</b>						
	AIR HOSE D40MT3+SLEEVES	Z7 22049	1	○		○
	AIR HOSE D40MT5+SLEEVES	Z7 22362	1	○		○
	AIR HOSE D50MT3+SLEEVES	Z7 22062	1	○		○
	AIR HOSE D50MT5+SLEEVES	Z7 22363	1	○	○	○
	AIR HOSE D70MT3+SLEEVES	Z7 22063	1	○		○
	AIR HOSE D70MT5+SLEEVES	Z7 22364	1	○		○
	FLEX HOSE D40MT3+SLEEVES	Z7 22150	1	○		○
	FLEX HOSE D40MT5+SLEEVES	Z7 22360	1	○		○
	FLEX HOSE D50MT3+SLEEVES	Z7 22151	1	○		○
	FLEX HOSE D50MT5+SLEEVES	Z7 22361	1	○		○
	POLYURETHANE HOSE D40 3M +SLEEVES	Z7 22297	1	○		○
	POLYURETHANE HOSE D40 5M +SLEEVES	Z7 22365	1	○		○



## 3 motor single phase industrial vacuum cleaner for hazardous dust

Accessories		Ref. no.	Min. required	S3 L50 LC GV CC	S3 L50 LC L GV CC 3X	S3 L100 LC FM AU UKP
	POLYURETHANE HOSE D50 3M +SLEEVES	Z7 22298	1	○		○
	POLYURETHANE HOSE D50 5M +SLEEVES	Z7 22366	1	○		○
	POLYURETHANE HOSE D70 3M +SLEEVES	Z7 22299	1	○		○
	POLYURETHANE HOSE D70 5M +SLEEVES	Z7 22367	1	○		○
<b>Pipe Cleaner Nozzle</b>						
	CURVED BRUSH FOR PIPES D40/100 FE COMPL	Z7 22132	1	○		○
	CURVED BRUSH FOR PIPES D50/100 FE COMPL	Z7 22131	1	○		○
<b>Nozzle</b>						
	LIQ.SUCKER D50 MM400 INOX COMPLETE	Z7 22294	1	○		○
	LIQUIDS SUCKER D40 MM400 INOX COMPLETE	Z7 22296	1	○		○
	PACK10 RUBBERS FIX.NOZZLE MM600-700	Z8 20297	1	○		○
	PACK 10 STRIP MOBILE S. MM.400	Z8 23040	1	○		○
	PACK 10 STRIP MOBILE S. MM.500	Z8 23041	1	○		○
	PACK OF 10 RUBBERS 400 20086	Z8 20295	1	○		○











## 3 motor single phase industrial vacuum cleaner for hazardous dust

● Standard equipment, ○ Supplementary accessories, □ Mountable equipment












Accessories	Ref. no.	Min. required	S3 L50 LC FM AU	S3 L50 LC PBS AU UKP	S3 L100 LC L GV CC AU UKP
<b>Filter</b>					
	ABSOLUTE FILTER KIT M.125/1216	Z5 60357	1	○	○
	KIT STAR FILTER D460 L CLASS	40000338	1	○	○
	SAFETY FILTER BAG 460MM STD W SAFETY BLT	4084001244	1	○	○
	STAR FILTER KIT D460 M CLASS	40000492	1	○	○
<b>Other</b>					
	BRACKET EMPTYING BELT D460 COMPLETE	Z5 36074	1	○	○
	EMPTYING BELT D460 COMPLETE	Z5 36073	1	○	○
	HARMONIC SPRINGPIN LINK	Z7 20328	1	○	○
	KIT MECANICAL FLOAT S3B SS	4056000519	1	○	○
	TRIM BASKET KIT D460 L100	40000915	1	○	○
<b>Bag</b>					
	5PCS PAPER BAGS GS82	81584000	1	○	○
<b>Option</b>					
	EXTRACT CYCLONE D460 FE COMPLETE	Z5 60109	1	○	○
	KIT LIFTING MS2-S3	4056000493	1	○	○
	KIT LIQUIDS M.S3	4056000498	1	○	○
	KIT STAFFA SOLLEVAMENTO CONT. MODELLI CT	4056000394	1	○	○
<b>Vac Nozzle Fixed</b>					
	KIT FIX NOZZLE MM600 M.S2-S3	4056000487	1	○	○
<b>Assembly</b>					
	GRID AND VALVE D460 FE COMPLETE	Z5 60034	1	○	○
<b>Accessory Kit</b>					
	KIT AC.D50 EQUIPMENTS CLEANING	Z7 24156	1	○	○
	KIT AC.D50 INDUSTRIAL CLEANING	Z7 24151	1	○	○














## 3 motor single phase industrial vacuum cleaner for hazardous dust

	Accessories	Ref. no.	Min. required	S3 L50 LC FM AU	S3 L50 LC PBS AU UKP	S3 L100 LC L GV CC AU UKP
	KIT ACC.D.50 GENERAL CLEANING	Z7 24146	1	○	○	○
	KIT INLET FOR PAPER BAG D70 SS WITH	Z5 60375	1	○	○	○
	KIT INLET X PAPER BAG D.70 COMP.WITH	Z5 60351	1	○	○	○
<b>Vacuum Hose and Connection</b>						
	BENT CONNECTION D40 FE	Z7 21013	1	○	○	○
	BENT CONNECTION D50 FE	Z7 21012	1	○	○	○
	BENT CONNECTION D50 INOX	Z7 21034	1	○	○	○
	BENT CONNECTION D50/40 Z.PLT.	Z7 22015	1	○	○	○
	BENT CONNECTION D70 FE	Z7 21032	1	○	○	○
	CONNECTION JOINT D40 FE	Z7 21004	1	○	○	○
	CONNECTION JOINT D50 FE	Z7 21002	1	○	○	○
	CONNECTION JOINT D50 INOX	Z7 22241	1	○	○	○
	CONNECTION JOINT D70 FE	Z7 21000	1	○	○	○
	CONNECTION JOINT D70 INOX	Z7 22242	1	○	○	○

## 3 motor single phase industrial vacuum cleaner for hazardous dust

	Accessories	Ref. no.	Min. required	S3 L50 LC FM AU	S3 L50 LC PBS AU UKP	S3 L100 LC L GV CC AU UKP
	CONNECTION TUBE D70 INOX	Z7 22231	0	○	○	○
	CONNECTION TUBE D70 STEEL	Z7 21001	1	○	○	○
	QUICK COUPLING D40 FE COMPLETE	Z7 22186	1	○	○	○
	QUICK COUPLING D50 FE COMPLETE	Z7 22187	1	○	○	○
	REDUCER D70/40 FE	Z7 22002	1	○	○	○
	REDUCER IRON D70/50	Z7 22001	1	○	○	○
	REDUCER REGULATION D70/50 COMPLETE	Z7 22162	1	○	○	○
	REDUCER REGULATION D.70/40 COMPLETE	Z7 22164	1	○	○	○
<b>Cone Nozzle</b>						
	CONIC END D40/50/20 COMPLETE	Z7 22142	1	○	○	○
	CONIC END D50/20 COMPLETE	Z7 22141	1	○	○	○
	CONIC TUBE D40 RUBBER	Z7 21011	1	○	○	○

## 3 motor single phase industrial vacuum cleaner for hazardous dust












	Accessories	Ref. no.	Min. required	S3 L50 LC FM AU	S3 L50 LC PBS AU UKP	S3 L100 LC L GV CC AU UKP
	CONIC TUBE D50 RUBBER	Z7 21010	1	○	○	○
	CONIC TUBE D70 RUBBER	Z7 21009	1	○	○	○
<b>Crevice Nozzle</b>						
	CURVED FLAT LANCE D50 FE	Z7 21075	1	○	○	○
	CURVED FLAT LANCE D70 MM1000 PVC	Z7 24012	1	○	○	○
	FLAT LANCE D40 MM500 PVC	Z7 24014	1	○	○	○
	FLAT LANCE D40 ZINC PLT.	Z7 21027	1	○	○	○
	FLAT LANCE D50 MM500 PVC	Z7 24013	1	○	○	○
	FLAT LANCE D50 ZINC PLT.	Z7 21026	1	○	○	○
	FLAT LANCE D50/40 ZINC PLT.	Z7 22021	1	○	○	○
	FLAT LANCE D70 ZINC PLT.	Z7 21028	1	○	○	○
	FLAT LANCE DIAL D40 FE COMP.DIAL NYLON	Z7 22088	1	○	○	○














## 3 motor single phase industrial vacuum cleaner for hazardous dust

	Accessories	Ref. no.	Min. required	S3 L50 LC FM AU	S3 L50 LC PBS AU UKP	S3 L100 LC L GV CC AU UKP
	FLAT LANCE DIAL D40 FE COMPLETE DIAL	Z7 22024	1	○	○	○
	FLAT LANCE DIAL D50 FE COMP.DIAL NYLON	Z7 22089	1	○	○	○
	FLAT LANCE DIAL D50 FE COMPLETE DIAL	Z7 22023	1	○	○	○
	GREY NBR NOZZLE D50 120MM	Z7 21030	1	○	○	○
	SCRAPING SUCKER D40 FE	Z7 22033	1	○	○	○
	SCRAPING SUCKER D40 INOX	Z7 22277	1	○	○	○
	SCRAPING SUCKER D50 FE	Z7 22034	1	○	○	○
	SCRAPING SUCKER D50 INOX	Z7 22278	1	○	○	○
	SCRAPING SUCKER D70 MM 200	Z7 22090	1	○	○	○
<b>Hose and Connection</b>						
	BENT CONNECTION D40 INOX	Z7 21033	1	○	○	○
	CONNECTION JOINT D40 INOX	Z7 22240	1	○	○	○













## 3 motor single phase industrial vacuum cleaner for hazardous dust

	Accessories	Ref. no.	Min. required	S3 L50 LC FM AU	S3 L50 LC PBS AU UKP	S3 L100 LC L GV CC AU UKP
	G.REDUCER D70/40 INOX COMPLETE	Z7 22235	0	○	○	○
	REDUCER D70/40 INOX	Z7 22224	1	○	○	○
	REDUCER D70/50 INOX	Z7 22225	1	○	○	○
	REG.REDUCER D70/50 INOX COMPLETE	Z7 22236	0	○	○	○
	TIE D40-60	Z8 40040	1	○	○	○
<b>Extension Tube</b>						
	ALUMINIUM EXTENSION D50 MT1 INLET PIN	Z7 22385	1	○	○	○
	EXTENSION D40 MT.1 ALUMINIUM COMPLETE	Z7 22008	1	○	○	○
	EXTENSION D40 MT.2 ALUMINIUM COMPLETE	Z7 22007	1	○	○	○
	EXTENSION D40 MT.3 ALUMINIUM COMPLETE	Z7 22006	1	○	○	○
	EXTENSION D50 MT.1 ALUMINIUM COMPLETE	Z7 22005	1	○	○	○
	EXTENSION D50 MT.2 ALUMINIUM COMPLETE	Z7 22004	1	○	○	○











## 3 motor single phase industrial vacuum cleaner for hazardous dust

	Accessories	Ref. no.	Min. required	S3 L50 LC FM AU	S3 L50 LC PBS AU UKP	S3 L100 LC L GV CC AU UKP
	EXTENSION D50 MT.3 ALUMINIUM COMPLETE	Z7 22003	1	○	○	○
	HANDGRIP D40 ALUMINIUM COMPLETE	Z7 22026	1	○	○	○
	HANDGRIP D40 CHROME PLT. COMPLETE	Z7 22121	1	○	○	○
	HANDGRIP D50 ALUMINIUM COMPLETE	Z7 22025	1	○	○	○
	HANDGRIP D50 CHROME PLT. COMPLETE	Z7 22122	1	○	○	○
<b>Vac Nozzle Wet</b>						
	LIQ.SUCKER D40 MM500 FE COMPLETE	Z7 22168	1	○	○	○
	LIQ.SUCKER D50 MM500 FE COMPLETE	Z7 22167	1	○	○	○
	LIQUIDS SUCKER D40 MM400 FE COMPLETE	Z7 22028	1	○	○	○
	LIQUIDS SUCKER D50 MM400 FE COMPLETE	Z7 22027	1	○	○	○
<b>Vac Nozzle Dry</b>						
	AUTOBUS SUCKER D50 200 AL. COMPLETE	Z7 22170	1	○	○	○
	BRUSH D40 MM220 30 COMPLETE	Z7 22193	1	○	○	○



## 3 motor single phase industrial vacuum cleaner for hazardous dust

	Accessories	Ref. no.	Min. required	S3 L50 LC FM AU	S3 L50 LC PBS AU UKP	S3 L100 LC L GV CC AU UKP
	BRUSH D40 MM220 90 COMPLETE	Z7 22042	1	○	○	○
	BRUSH D40 MM300 30 COMPLETE	Z7 22194	1	○	○	○
	BRUSH D40 MM300 90 COMPLETE	Z7 22043	1	○	○	○
	BRUSH D40 MM400 30 COMPLETE	Z7 22195	1	○	○	○
	BRUSH D40 MM400 90 COMPLETE	Z7 22044	1	○	○	○
	BRUSH D50 MM220 30 COMPLETE	Z7 22196	1	○	○	○
	BRUSH D50 MM220 90 COMPLETE	Z7 22038	1	○	○	○
	BRUSH D50 MM300 30 COMPLETE	Z7 22197	1	○	○	○
	BRUSH D50 MM300 90 COMPLETE	Z7 22039	1	○	○	○
	BRUSH D50 MM400 30 COMPLETE	Z7 22198	1	○	○	○
	BRUSH D50 MM400 90 COMPLETE	Z7 22040	1	○	○	○
	MOB.SUCKER D50 MM500 FE COMPLETE	Z7 22147	1	○	○	○












## 3 motor single phase industrial vacuum cleaner for hazardous dust

	Accessories	Ref. no.	Min. required	S3 L50 LC FM AU	S3 L50 LC PBS AU UKP	S3 L100 LC L GV CC AU UKP
	MOB.SUCKER STRIP D40 MM300 FE COMPLETE	Z7 22174	1	○	○	○
	MOB.SUCKER STRIP D40 MM400 FE COMPLETE	Z7 22138	1	○	○	○
	MOB.SUCKER STRIP D50 MM300 FE COMPLETE	Z7 22175	1	○	○	○
	MOB.SUCKER STRIP D50 MM400 FE COMPLETE	Z7 22137	1	○	○	○
	MOB.SUCKER STRIP D50 MM500 FE COMPLETE	Z7 22148	1	○	○	○
	MOBILE SUCKER D40 MM300 FE COMPLETE	Z7 22171	1	○	○	○
	MOBILE SUCKER D40 MM400 FE COMPLETE	Z7 22030	1	○	○	○
	MOBILE SUCKER D50 MM300 FE COMPLETE	Z7 22172	1	○	○	○
	MOBILE SUCKER D50 MM400 FE COMPLETE	Z7 22029	1	○	○	○
	SUCKER D40 MM400 ALUMINIUM	Z7 22031	1	○	○	○
	SUCKER D50 MM400 ALUMINIUM	Z7 22032	1	○	○	○
	SUCKER X FURNACES D40 MM400 FE COMPLETE	Z7 22272	1	○	○	○



## 3 motor single phase industrial vacuum cleaner for hazardous dust

Accessories		Ref. no.	Min. required	S3 L50 LC FM AU	S3 L50 LC PBS AU UKP	S3 L100 LC L GV CC AU UKP
	SUCKER X FURNACES D50 MM400 FE COMPLETE	Z7 22273	1	○	○	○
<b>Round Brush Nozzle</b>						
	PAINTBRUSH D50/100 BRISTLES COMPLETE	Z7 22047	1	○	○	○
	PAINTBRUSH D50/100 STEEL COMPLETE	Z7 22048	1	○	○	○
<b>Hose Vacuum Cleaner</b>						
	AIR HOSE D40MT3+SLEEVES	Z7 22049	1	○	○	○
	AIR HOSE D40MT5+SLEEVES	Z7 22362	1	○	○	○
	AIR HOSE D50MT3+SLEEVES	Z7 22062	1	○	○	○
	AIR HOSE D50MT5+SLEEVES	Z7 22363	1	○	○	○
	AIR HOSE D70MT3+SLEEVES	Z7 22063	1	○	○	○
	AIR HOSE D70MT5+SLEEVES	Z7 22364	1	○	○	○
	FLEX HOSE D40MT3+SLEEVES	Z7 22150	1	○	○	○
	FLEX HOSE D40MT5+SLEEVES	Z7 22360	1	○	○	○



## 3 motor single phase industrial vacuum cleaner for hazardous dust

Accessories		Ref. no.	Min. required	S3 L50 LC FM AU	S3 L50 LC PBS AU UKP	S3 L100 LC L GV CC AU UKP
	FLEX HOSE D50MT3+SLEEVES	Z7 22151	1	○	○	○
	FLEX HOSE D50MT5+SLEEVES	Z7 22361	1	○	○	○
	POLYURETHANE HOSE D40 3M +SLEEVES	Z7 22297	1	○	○	○
	POLYURETHANE HOSE D40 5M +SLEEVES	Z7 22365	1	○	○	○
	POLYURETHANE HOSE D50 3M +SLEEVES	Z7 22298	1	○	○	○
	POLYURETHANE HOSE D50 5M +SLEEVES	Z7 22366	1	○	○	○
	POLYURETHANE HOSE D70 3M +SLEEVES	Z7 22299	1	○	○	○
	POLYURETHANE HOSE D70 5M +SLEEVES	Z7 22367	1	○	○	○
<b>Pipe Cleaner Nozzle</b>						
	CURVED BRUSH FOR PIPES D40/100 FE COMPL	Z7 22132	1	○	○	○
	CURVED BRUSH FOR PIPES D50/100 FE COMPL	Z7 22131	1	○	○	○
<b>Nozzle</b>						
	LIQ. SUCKER D50 MM400 INOX COMPLETE	Z7 22294	1	○	○	○

3 motor single phase industrial vacuum cleaner for hazardous dust

Accessories		Ref. no.	Min. required	S3 L50 LC FM AU	S3 L50 LC PBS AU UKP	S3 L100 LC L GV CC AU UKP
	LIQUIDS SUCKER D40 MM400 INOX COMPLETE	Z7 22296	1	○	○	○
	PACK10 RUBBERS FIX.NOZZLE MM600-700	Z8 20297	1	○	○	○
	PACK 10 STRIP MOBILE S. MM.400	Z8 23040	1	○	○	○
	PACK 10 STRIP MOBILE S. MM.500	Z8 23041	1	○	○	○
	PACK OF 10 RUBBERS 400 20086	Z8 20295	1	○	○	○










● Standard equipment, ○ Supplementary accessories, □ Mountable equipment

Accessories		Ref. no.	Min. required	S3 L100 LC L GV CC AU V110 UKP	S3 MC LP UKP	S3 HC LP UKP
<b>Filter</b>						
	ABSOLUTE FILTER KIT M.125/1216	Z5 60357	1	○	○	○
	KIT STAR FILTER D460 L CLASS	40000338	1	○	○	○
	SAFETY FILTER BAG 460MM STD W SAFETY BLT	4084001244	1	○	○	○
	STAR FILTER KIT D460 M CLASS	40000492	1	○	○	○
<b>Other</b>						
	BRACKET EMPTYING BELT D460 COMPLETE	Z5 36074	1	○	○	○
	EMPTYING BELT D460 COMPLETE	Z5 36073	1	○	○	○
	HARMONIC SPRINGPIN LINK	Z7 20328	1	○	○	○
	KIT MECANICAL FLOAT S3B SS	4056000519	1	○	○	○
	TRIM BASKET KIT D460 L100	40000915	1	○	○	○
<b>Bag</b>						
	5PCS PAPER BAGS GS82	81584000	1	○	○	○
<b>Option</b>						
	EXTRACT CYCLONE D460 FE COMPLETE	Z5 60109	1	○	○	○
	KIT LIFTING MS2-S3	4056000493	1	○	○	○
	KIT LIQUIDS M.S3	4056000498	1	○	○	○
	KIT STAFFA SOLLEVAMENTO CONT. MODELLI CT	4056000394	1	○	○	○
<b>Vac Nozzle Fixed</b>						




























## 3 motor single phase industrial vacuum cleaner for hazardous dust

Accessories	Ref. no.	Min. required	S3 L100 GV CC AU V110 UKP	LC L	S3 MC LP UKP	S3 HC LP UKP
 KIT FIX NOZZLE MM600 M.S2-S3	4056000487	1	○		○	○
<b>Assembly</b>						
GRID AND VALVE D460 FE COMPLETE	Z5 60034	1	○		○	○
<b>Accessory Kit</b>						
 KIT AC.D50 EQUIPMENTS CLEANING	Z7 24156	1	○		○	○
 KIT AC.D50 INDUSTRIAL CLEANING	Z7 24151	1	○		○	○
 KIT ACC.D.50 GENERAL CLEANING	Z7 24146	1	○		○	○
KIT INLET FOR PAPER BAG D70 SS WITH	Z5 60375	1	○		○	○
KIT INLET X PAPER BAG D.70 COMP.WITH	Z5 60351	1	○		○	○
<b>Vacuum Hose and Connection</b>						
 BENT CONNECTION D40 FE	Z7 21013	1	○		○	○
 BENT CONNECTION D50 FE	Z7 21012	1	○		○	○
 BENT CONNECTION D50 INOX	Z7 21034	1	○		○	○
 BENT CONNECTION D50/40 Z.PLT.	Z7 22015	1	○		○	○
BENT CONNECTION D70 FE	Z7 21032	1	○		○	○
 CONNECTION JOINT D40 FE	Z7 21004	1	○		○	○

## 3 motor single phase industrial vacuum cleaner for hazardous dust

	Accessories	Ref. no.	Min. required	S3 L100 GV CC AU V110 UKP	LC L S3 MC LP UKP	LC L S3 HC LP UKP
	CONNECTION JOINT D50 FE	Z7 21002	1	○	○	○
	CONNECTION JOINT D50 INOX	Z7 22241	1	○	○	○
	CONNECTION JOINT D70 FE	Z7 21000	1	○	○	○
	CONNECTION JOINT D70 INOX	Z7 22242	1	○	○	○
	CONNECTION TUBE D70 INOX	Z7 22231	0	○	○	○
	CONNECTION TUBE D70 STEEL	Z7 21001	1	○	○	○
	QUICK COUPLING D40 FE COMPLETE	Z7 22186	1	○	○	○
	QUICK COUPLING D50 FE COMPLETE	Z7 22187	1	○	○	○
	REDUCER D70/40 FE	Z7 22002	1	○	○	○
	REDUCER IRON D70/50	Z7 22001	1	○	○	○
	REDUCER REGULATION D70/50 COMPLETE	Z7 22162	1	○	○	○
	REDUCER REGULATION D.70/40 COMPLETE	Z7 22164	1	○	○	○

## 3 motor single phase industrial vacuum cleaner for hazardous dust












Accessories	Ref. no.	Min. required	S3 L100 GV CC AU V110 UKP	LC L	S3 MC LP UKP	S3 HC LP UKP
<b>Cone Nozzle</b>						
	CONIC END D40/50/20 COMPLETE	Z7 22142	1	○	○	○
	CONIC END D50/20 COMPLETE	Z7 22141	1	○	○	○
	CONIC TUBE D40 RUBBER	Z7 21011	1	○	○	○
	CONIC TUBE D50 RUBBER	Z7 21010	1	○	○	○
	CONIC TUBE D70 RUBBER	Z7 21009	1	○	○	○
<b>Crevice Nozzle</b>						
	CURVED FLAT LANCE D50 FE	Z7 21075	1	○	○	○
	CURVED FLAT LANCE D70 MM1000 PVC	Z7 24012	1	○	○	○
	FLAT LANCE D40 MM500 PVC	Z7 24014	1	○	○	○
	FLAT LANCE D40 ZINC PLT.	Z7 21027	1	○	○	○
	FLAT LANCE D50 MM500 PVC	Z7 24013	1	○	○	○
	FLAT LANCE D50 ZINC PLT.	Z7 21026	1	○	○	○

## 3 motor single phase industrial vacuum cleaner for hazardous dust











	Accessories	Ref. no.	Min. required	S3 L100 LC L GV CC AU V110 UKP	S3 MC LP UKP	S3 HC LP UKP
	FLAT LANCE D50/40 ZINC PLT.	Z7 22021	1	○	○	○
	FLAT LANCE D70 ZINC PLT.	Z7 21028	1	○	○	○
	FLAT LANCE DIAL D40 FE COMP.DIAL NYLON	Z7 22088	1	○	○	○
	FLAT LANCE DIAL D40 FE COMPLETE DIAL	Z7 22024	1	○	○	○
	FLAT LANCE DIAL D50 FE COMP.DIAL NYLON	Z7 22089	1	○	○	○
	FLAT LANCE DIAL D50 FE COMPLETE DIAL	Z7 22023	1	○	○	○
	GREY NBR NOZZLE D50 120MM	Z7 21030	1	○	○	○
	SCRAPING SUCKER D40 FE	Z7 22033	1	○	○	○
	SCRAPING SUCKER D40 INOX	Z7 22277	1	○	○	○
	SCRAPING SUCKER D50 FE	Z7 22034	1	○	○	○
	SCRAPING SUCKER D50 INOX	Z7 22278	1	○	○	○
	SCRAPING SUCKER D70 MM 200	Z7 22090	1	○	○	○



## 3 motor single phase industrial vacuum cleaner for hazardous dust

Accessories		Ref. no.	Min. required	S3 L100 GV CC AU V110 UKP	LC L	S3 MC LP UKP	S3 HC LP UKP
<b>Hose and Connection</b>							
	BENT CONNECTION D40 INOX	Z7 21033	1	○		○	○
	CONNECTION JOINT D40 INOX	Z7 22240	1	○		○	○
	G.REDUCER D70/40 INOX COMPLETE	Z7 22235	0	○		○	○
	REDUCER D70/40 INOX	Z7 22224	1	○		○	○
	REDUCER D70/50 INOX	Z7 22225	1	○		○	○
	REG.REDUCER D70/50 INOX COMPLETE	Z7 22236	0	○		○	○
	TIE D40-60	Z8 40040	1	○		○	○
<b>Extension Tube</b>							
	ALUMINIUM EXTENSION D50 MT1 INLET PIN	Z7 22385	1	○		○	○
	EXTENSION D40 MT.1 ALUMINIUM COMPLETE	Z7 22008	1	○		○	○
	EXTENSION D40 MT.2 ALUMINIUM COMPLETE	Z7 22007	1	○		○	○
	EXTENSION D40 MT.3 ALUMINIUM COMPLETE	Z7 22006	1	○		○	○

## 3 motor single phase industrial vacuum cleaner for hazardous dust



	Accessories	Ref. no.	Min. required	S3 L100 LC L GV CC AU V110 UKP	S3 MC LP UKP	S3 HC LP UKP
	EXTENSION D50 MT.1 ALUMINIUM COMPLETE	Z7 22005	1	○	○	○
	EXTENSION D50 MT.2 ALUMINIUM COMPLETE	Z7 22004	1	○	○	○
	EXTENSION D50 MT.3 ALUMINIUM COMPLETE	Z7 22003	1	○	○	○
	HANDGRIP D40 ALUMINIUM COMPLETE	Z7 22026	1	○	○	○
	HANDGRIP D40 CHROME PLT. COMPLETE	Z7 22121	1	○	○	○
	HANDGRIP D50 ALUMINIUM COMPLETE	Z7 22025	1	○	○	○
	HANDGRIP D50 CHROME PLT. COMPLETE	Z7 22122	1	○	○	○
<b>Vac Nozzle Wet</b>						
	LIQ.SUCKER D40 MM500 FE COMPLETE	Z7 22168	1	○	○	○
	LIQ.SUCKER D50 MM500 FE COMPLETE	Z7 22167	1	○	○	○
	LIQUIDS SUCKER D40 MM400 FE COMPLETE	Z7 22028	1	○	○	○
	LIQUIDS SUCKER D50 MM400 FE COMPLETE	Z7 22027	1	○	○	○
<b>Vac Nozzle Dry</b>						

## 3 motor single phase industrial vacuum cleaner for hazardous dust

	Accessories	Ref. no.	Min. required	S3 L100 LC L GV CC AU V110 UKP	S3 MC LP UKP	S3 HC LP UKP
	AUTOBUS SUCKER D50 200 AL. COMPLETE	Z7 22170	1	○	○	○
	BRUSH D40 MM220 30 COMPLETE	Z7 22193	1	○	○	○
	BRUSH D40 MM220 90 COMPLETE	Z7 22042	1	○	○	○
	BRUSH D40 MM300 30 COMPLETE	Z7 22194	1	○	○	○
	BRUSH D40 MM300 90 COMPLETE	Z7 22043	1	○	○	○
	BRUSH D40 MM400 30 COMPLETE	Z7 22195	1	○	○	○
	BRUSH D40 MM400 90 COMPLETE	Z7 22044	1	○	○	○
	BRUSH D50 MM220 30 COMPLETE	Z7 22196	1	○	○	○
	BRUSH D50 MM220 90 COMPLETE	Z7 22038	1	○	○	○
	BRUSH D50 MM300 30 COMPLETE	Z7 22197	1	○	○	○
	BRUSH D50 MM300 90 COMPLETE	Z7 22039	1	○	○	○
	BRUSH D50 MM400 30 COMPLETE	Z7 22198	1	○	○	○



## 3 motor single phase industrial vacuum cleaner for hazardous dust












	Accessories	Ref. no.	Min. required	S3 L100 LC L GV CC AU V110 UKP	S3 MC LP UKP	S3 HC LP UKP
	BRUSH D50 MM400 90 COMPLETE	Z7 22040	1	○	○	○
	MOB.SUCKER D50 MM500 FE COMPLETE	Z7 22147	1	○	○	○
	MOB.SUCKER STRIP D40 MM300 FE COMPLETE	Z7 22174	1	○	○	○
	MOB.SUCKER STRIP D40 MM400 FE COMPLETE	Z7 22138	1	○	○	○
	MOB.SUCKER STRIP D50 MM300 FE COMPLETE	Z7 22175	1	○	○	○
	MOB.SUCKER STRIP D50 MM400 FE COMPLETE	Z7 22137	1	○	○	○
	MOB.SUCKER STRIP D50 MM500 FE COMPLETE	Z7 22148	1	○	○	○
	MOBILE SUCKER D40 MM300 FE COMPLETE	Z7 22171	1	○	○	○
	MOBILE SUCKER D40 MM400 FE COMPLETE	Z7 22030	1	○	○	○
	MOBILE SUCKER D50 MM300 FE COMPLETE	Z7 22172	1	○	○	○
	MOBILE SUCKER D50 MM400 FE COMPLETE	Z7 22029	1	○	○	○
	SUCKER D40 MM400 ALUMINIUM	Z7 22031	1	○	○	○







## 3 motor single phase industrial vacuum cleaner for hazardous dust

Accessories	Ref. no.	Min. required	S3 L100 GV CC AU V110 UKP	LC L	S3 MC LP UKP	S3 HC LP UKP
 SUCKER D50 MM400 ALUMINIUM	Z7 22032	1	○		○	○
 SUCKER X FURNACES D40 MM400 FE COMPLETE	Z7 22272	1	○		○	○
 SUCKER X FURNACES D50 MM400 FE COMPLETE	Z7 22273	1	○		○	○
<b>Round Brush Nozzle</b>						
 PAINTBRUSH D50/100 BRISTLES COMPLETE	Z7 22047	1	○		○	○
 PAINTBRUSH D50/100 STEEL COMPLETE	Z7 22048	1	○		○	○
<b>Hose Vacuum Cleaner</b>						
 AIR HOSE D40MT3+SLEEVES	Z7 22049	1	○		○	○
 AIR HOSE D40MT5+SLEEVES	Z7 22362	1	○		○	○
 AIR HOSE D50MT3+SLEEVES	Z7 22062	1	○		○	○
 AIR HOSE D50MT5+SLEEVES	Z7 22363	1	○		○	○
 AIR HOSE D70MT3+SLEEVES	Z7 22063	1	○		○	○
 AIR HOSE D70MT5+SLEEVES	Z7 22364	1	○		○	○



## 3 motor single phase industrial vacuum cleaner for hazardous dust

Accessories		Ref. no.	Min. required	S3 L100 GV CC AU V110 UKP	LC L	S3 MC LP UKP	S3 HC LP UKP
	FLEX HOSE D40MT3+SLEEVES	Z7 22150	1	○		○	○
	FLEX HOSE D40MT5+SLEEVES	Z7 22360	1	○		○	○
	FLEX HOSE D50MT3+SLEEVES	Z7 22151	1	○		○	○
	FLEX HOSE D50MT5+SLEEVES	Z7 22361	1	○		○	○
	POLYURETHANE HOSE D40 3M +SLEEVES	Z7 22297	1	○		○	○
	POLYURETHANE HOSE D40 5M +SLEEVES	Z7 22365	1	○		○	○
	POLYURETHANE HOSE D50 3M +SLEEVES	Z7 22298	1	○		○	○
	POLYURETHANE HOSE D50 5M +SLEEVES	Z7 22366	1	○		○	○
	POLYURETHANE HOSE D70 3M +SLEEVES	Z7 22299	1	○		○	○
	POLYURETHANE HOSE D70 5M +SLEEVES	Z7 22367	1	○		○	○
<b>Pipe Cleaner Nozzle</b>							
	CURVED BRUSH FOR PIPES D40/100 FE COMPL	Z7 22132	1	○		○	○

## 3 motor single phase industrial vacuum cleaner for hazardous dust









Accessories		Ref. no.	Min. required	S3 L100 LC L GV CC AU V110 UKP	S3 MC LP UKP	S3 HC LP UKP
	CURVED BRUSH FOR PIPES D50/100 FE COMPL	Z7 22131	1	○	○	○
<b>Nozzle</b>						
	LIQ.SUCKER D50 MM400 INOX COMPLETE	Z7 22294	1	○	○	○
	LIQUIDS SUCKER D40 MM400 INOX COMPLETE	Z7 22296	1	○	○	○
	PACK10 RUBBERS FIX.NOZZLE MM600-700	Z8 20297	1	○	○	○
	PACK 10 STRIP MOBILE S. MM.400	Z8 23040	1	○	○	○
	PACK 10 STRIP MOBILE S. MM.500	Z8 23041	1	○	○	○
	PACK OF 10 RUBBERS 400 20086	Z8 20295	1	○	○	○

● Standard equipment, ○ Supplementary accessories, □ Mountable equipment













Accessories		Ref. no.	Min. required	S3 HC LP V110 UKP	S3CB L100 LC FM	S3CB L100 LC FM V110 UKP
<b>Filter</b>						
	ABSOLUTE FILTER KIT M.125/1216	Z5 60357	1	○		
	KIT STAR FILTER D460 L CLASS	40000338	1	○		
	SAFETY FILTER BAG 460MM STD W SAFETY BLT	4084001244	1	○		
	STAR FILTER KIT D460 M CLASS	40000492	1	○		
<b>Other</b>						
	BRACKET EMPTYING BELT D460 COMPLETE	Z5 36074	1	○		
	EMPTYING BELT D460 COMPLETE	Z5 36073	1	○		
	HARMONIC SPRINGPIN LINK	Z7 20328	1	○		
	KIT MECANICAL FLOAT S3B SS	4056000519	1	○		
	TRIM BASKET KIT D460 L100	40000915	1	○		
<b>Bag</b>						
	5PCS PAPER BAGS GS82	81584000	1	○		














## 3 motor single phase industrial vacuum cleaner for hazardous dust

Accessories		Ref. no.	Min. required	S3 HC LP V110 UKP	S3CB L100 LC FM	S3CB L100 LC FM V110 UKP
<b>Option</b>						
	EXTRACT CYCLONE D460 FE COMPLETE	Z5 60109	1	○		
	KIT LIFTING MS2-S3	4056000493	1	○		
	KIT LIQUIDS M.S3	4056000498	1	○		
	KIT STAFFA SOLLEVAMENTO CONT. MODELLI CT	4056000394	1	○		
<b>Vac Nozzle Fixed</b>						
	KIT FIX NOZZLE MM600 M.S2-S3	4056000487	1	○		
<b>Assembly</b>						
	GRID AND VALVE D460 FE COMPLETE	Z5 60034	1	○		
<b>Accessory Kit</b>						
	KIT AC.D50 EQUIPMENTS CLEANING	Z7 24156	1	○		
	KIT AC.D50 INDUSTRIAL CLEANING	Z7 24151	1	○		
	KIT ACC.D.50 GENERAL CLEANING	Z7 24146	1	○		
	KIT INLET FOR PAPER BAG D70 SS WITH	Z5 60375	1	○		
	KIT INLET X PAPER BAG D.70 COMP.WITH	Z5 60351	1	○		
<b>Vacuum Hose and Connection</b>						
	BENT CONNECTION D40 FE	Z7 21013	1	○		
	BENT CONNECTION D50 FE	Z7 21012	1	○		
	BENT CONNECTION D50 INOX	Z7 21034	1	○		
	BENT CONNECTION D50/40 Z.PLT.	Z7 22015	1	○		
	BENT CONNECTION D70 FE	Z7 21032	1	○		













## 3 motor single phase industrial vacuum cleaner for hazardous dust

	Accessories	Ref. no.	Min. required	S3 HC LP V110 UKP	S3CB L100 LC FM	S3CB L100 LC FM V110 UKP
	CONNECTION JOINT D40 FE	Z7 21004	1	○		
	CONNECTION JOINT D50 FE	Z7 21002	1	○		
	CONNECTION JOINT D50 INOX	Z7 22241	1	○		
	CONNECTION JOINT D70 FE	Z7 21000	1	○		
	CONNECTION JOINT D70 INOX	Z7 22242	1	○		
	CONNECTION TUBE D70 INOX	Z7 22231	0	○		
	CONNECTION TUBE D70 STEEL	Z7 21001	1	○		
	QUICK COUPLING D40 FE COMPLETE	Z7 22186	1	○		
	QUICK COUPLING D50 FE COMPLETE	Z7 22187	1	○		
	REDUCER D70/40 FE	Z7 22002	1	○		
	REDUCER IRON D70/50	Z7 22001	1	○	•	•
	REDUCER REGULATION D70/50 COMPLETE	Z7 22162	1	○		












## 3 motor single phase industrial vacuum cleaner for hazardous dust

Accessories		Ref. no.	Min. required	S3 HC LP V110 UKP	S3CB L100 LC FM	S3CB L100 LC FM V110 UKP
	REDUCER REGULATION D.70/40 COMPLETE	Z7 22164	1	○		
<b>Cone Nozzle</b>						
	CONIC END D40/50/20 COMPLETE	Z7 22142	1	○		
	CONIC END D50/20 COMPLETE	Z7 22141	1	○		
	CONIC TUBE D40 RUBBER	Z7 21011	1	○		
	CONIC TUBE D50 RUBBER	Z7 21010	1	○	●	●
	CONIC TUBE D70 RUBBER	Z7 21009	1	○		
<b>Crevice Nozzle</b>						
	CURVED FLAT LANCE D50 FE	Z7 21075	1	○		
	CURVED FLAT LANCE D70 MM1000 PVC	Z7 24012	1	○		
	FLAT LANCE D40 MM500 PVC	Z7 24014	1	○		
	FLAT LANCE D40 ZINC PLT.	Z7 21027	1	○		
	FLAT LANCE D50 MM500 PVC	Z7 24013	1	○		

## 3 motor single phase industrial vacuum cleaner for hazardous dust













Accessories	Ref. no.	Min. required	S3 HC LP V110 UKP	S3CB L100 LC FM	S3CB L100 LC FM V110 UKP
 FLAT LANCE D50 ZINC PLT.	Z7 21026	1	○	●	●
 FLAT LANCE D50/40 ZINC PLT.	Z7 22021	1	○		
 FLAT LANCE D70 ZINC PLT.	Z7 21028	1	○		
 FLAT LANCE DIAL D40 FE COMP.DIAL NYLON	Z7 22088	1	○		
 FLAT LANCE DIAL D40 FE COMPLETE DIAL	Z7 22024	1	○		
 FLAT LANCE DIAL D50 FE COMP.DIAL NYLON	Z7 22089	1	○		
 FLAT LANCE DIAL D50 FE COMPLETE DIAL	Z7 22023	1	○		
 GREY NBR NOZZLE D50 120MM	Z7 21030	1	○		
 SCRAPING SUCKER D40 FE	Z7 22033	1	○		
 SCRAPING SUCKER D40 INOX	Z7 22277	1	○		
 SCRAPING SUCKER D50 FE	Z7 22034	1	○		
 SCRAPING SUCKER D50 INOX	Z7 22278	1	○		

## 3 motor single phase industrial vacuum cleaner for hazardous dust













Accessories		Ref. no.	Min. required	S3 HC LP V110 UKP	S3CB L100 LC FM	S3CB L100 LC FM V110 UKP
	SCRAPING SUCKER D70 MM 200	Z7 22090	1	○		
<b>Hose and Connection</b>						
	BENT CONNECTION D40 INOX	Z7 21033	1	○		
	CONNECTION JOINT D40 INOX	Z7 22240	1	○		
	G.REDUCER D70/40 INOX COMPLETE	Z7 22235	0	○		
	REDUCER D70/40 INOX	Z7 22224	1	○		
	REDUCER D70/50 INOX	Z7 22225	1	○		
	REG.REDUCER D70/50 INOX COMPLETE	Z7 22236	0	○		
	TIE D40-60	Z8 40040	1	○		
<b>Extension Tube</b>						
	ALUMINIUM EXTENSION D50 MT1 INLET PIN	Z7 22385	1	○		
	EXTENSION D40 MT.1 ALUMINIUM COMPLETE	Z7 22008	1	○		
	EXTENSION D40 MT.2 ALUMINIUM COMPLETE	Z7 22007	1	○		



## 3 motor single phase industrial vacuum cleaner for hazardous dust













Accessories		Ref. no.	Min. required	S3 HC LP V110 UKP	S3CB L100 LC FM	S3CB L100 LC FM V110 UKP
	EXTENSION D40 MT.3 ALUMINIUM COMPLETE	Z7 22006	1	○		
	EXTENSION D50 MT.1 ALUMINIUM COMPLETE	Z7 22005	1	○		
	EXTENSION D50 MT.2 ALUMINIUM COMPLETE	Z7 22004	1	○		
	EXTENSION D50 MT.3 ALUMINIUM COMPLETE	Z7 22003	1	○		
	HANDGRIP D40 ALUMINIUM COMPLETE	Z7 22026	1	○		
	HANDGRIP D40 CHROME PLT. COMPLETE	Z7 22121	1	○		
	HANDGRIP D50 ALUMINIUM COMPLETE	Z7 22025	1	○	●	●
	HANDGRIP D50 CHROME PLT. COMPLETE	Z7 22122	1	○		
<b>Vac Nozzle Wet</b>						
	LIQ.SUCKER D40 MM500 FE COMPLETE	Z7 22168	1	○		
	LIQ.SUCKER D50 MM500 FE COMPLETE	Z7 22167	1	○		
	LIQUIDS SUCKER D40 MM400 FE COMPLETE	Z7 22028	1	○		
	LIQUIDS SUCKER D50 MM400 FE COMPLETE	Z7 22027	1	○		

## 3 motor single phase industrial vacuum cleaner for hazardous dust











Accessories	Ref. no.	Min. required	S3 HC LP V110 UKP	S3CB L100 LC FM	S3CB L100 LC FM V110 UKP
<b>Vac Nozzle Dry</b>					
	AUTOBUS SUCKER D50 200 AL. COMPLETE	Z7 22170	1	○	
	BRUSH D40 MM220 30 COMPLETE	Z7 22193	1	○	
	BRUSH D40 MM220 90 COMPLETE	Z7 22042	1	○	
	BRUSH D40 MM300 30 COMPLETE	Z7 22194	1	○	
	BRUSH D40 MM300 90 COMPLETE	Z7 22043	1	○	
	BRUSH D40 MM400 30 COMPLETE	Z7 22195	1	○	
	BRUSH D40 MM400 90 COMPLETE	Z7 22044	1	○	
	BRUSH D50 MM220 30 COMPLETE	Z7 22196	1	○	
	BRUSH D50 MM220 90 COMPLETE	Z7 22038	1	○	
	BRUSH D50 MM300 30 COMPLETE	Z7 22197	1	○	
	BRUSH D50 MM300 90 COMPLETE	Z7 22039	1	○	
	BRUSH D50 MM400 30 COMPLETE	Z7 22198	1	○	















## 3 motor single phase industrial vacuum cleaner for hazardous dust

Accessories	Ref. no.	Min. required	S3 HC LP V110 UKP	S3CB L100 LC FM	S3CB L100 LC FM V110 UKP
 BRUSH D50 MM400 90 COMPLETE	Z7 22040	1	○		
 MOB.SUCKER D50 MM500 FE COMPLETE	Z7 22147	1	○		
 MOB.SUCKER STRIP D40 MM300 FE COMPLETE	Z7 22174	1	○		
 MOB.SUCKER STRIP D40 MM400 FE COMPLETE	Z7 22138	1	○		
 MOB.SUCKER STRIP D50 MM300 FE COMPLETE	Z7 22175	1	○		
 MOB.SUCKER STRIP D50 MM400 FE COMPLETE	Z7 22137	1	○		
 MOB.SUCKER STRIP D50 MM500 FE COMPLETE	Z7 22148	1	○		
 MOBILE SUCKER D40 MM300 FE COMPLETE	Z7 22171	1	○		
 MOBILE SUCKER D40 MM400 FE COMPLETE	Z7 22030	1	○		
 MOBILE SUCKER D50 MM300 FE COMPLETE	Z7 22172	1	○	●	●
 MOBILE SUCKER D50 MM400 FE COMPLETE	Z7 22029	1	○		
 SUCKER D40 MM400 ALUMINIUM	Z7 22031	1	○		




## 3 motor single phase industrial vacuum cleaner for hazardous dust

Accessories		Ref. no.	Min. required	S3 HC LP V110 UKP	S3CB L100 LC FM	S3CB L100 LC FM V110 UKP
	SUCKER D50 MM400 ALUMINIUM	Z7 22032	1	○		
	SUCKER X FURNACES D40 MM400 FE COMPLETE	Z7 22272	1	○		
	SUCKER X FURNACES D50 MM400 FE COMPLETE	Z7 22273	1	○		
<b>Round Brush Nozzle</b>						
	PAINTBRUSH D50/100 BRISTLES COMPLETE	Z7 22047	1	○		
	PAINTBRUSH D50/100 STEEL COMPLETE	Z7 22048	1	○		
<b>Hose Vacuum Cleaner</b>						
	AIR HOSE D40MT3+SLEEVES	Z7 22049	1	○		
	AIR HOSE D40MT5+SLEEVES	Z7 22362	1	○		
	AIR HOSE D50MT3+SLEEVES	Z7 22062	1	○		
	AIR HOSE D50MT5+SLEEVES	Z7 22363	1	○	●	●
	AIR HOSE D70MT3+SLEEVES	Z7 22063	1	○		
	AIR HOSE D70MT5+SLEEVES	Z7 22364	1	○		

## 3 motor single phase industrial vacuum cleaner for hazardous dust

Accessories		Ref. no.	Min. required	S3 HC LP V110 UKP	S3CB L100 LC FM	S3CB L100 LC FM V110 UKP
	FLEX HOSE D40MT3+SLEEVES	Z7 22150	1	○		
	FLEX HOSE D40MT5+SLEEVES	Z7 22360	1	○		
	FLEX HOSE D50MT3+SLEEVES	Z7 22151	1	○		
	FLEX HOSE D50MT5+SLEEVES	Z7 22361	1	○		
	POLYURETHANE HOSE D40 3M +SLEEVES	Z7 22297	1	○		
	POLYURETHANE HOSE D40 5M +SLEEVES	Z7 22365	1	○		
	POLYURETHANE HOSE D50 3M +SLEEVES	Z7 22298	1	○		
	POLYURETHANE HOSE D50 5M +SLEEVES	Z7 22366	1	○		
	POLYURETHANE HOSE D70 3M +SLEEVES	Z7 22299	1	○		
	POLYURETHANE HOSE D70 5M +SLEEVES	Z7 22367	1	○		
<b>Pipe Cleaner Nozzle</b>						
	CURVED BRUSH FOR PIPES D40/100 FE COMPL	Z7 22132	1	○		
	CURVED BRUSH FOR PIPES D50/100 FE COMPL	Z7 22131	1	○		

## 3 motor single phase industrial vacuum cleaner for hazardous dust

Accessories	Ref. no.	Min. required	S3 HC LP V110 UKP	S3CB L100 LC FM	S3CB L100 LC FM V110 UKP
<b>Nozzle</b>					
	LIQ. SUCKER D50 MM400 INOX COMPLETE	Z7 22294	1	○	
	LIQUIDS SUCKER D40 MM400 INOX COMPLETE	Z7 22296	1	○	
	PACK10 RUBBERS FIX.NOZZLE MM600-700	Z8 20297	1	○	
	PACK 10 STRIP MOBILE S. MM.400	Z8 23040	1	○	
	PACK 10 STRIP MOBILE S. MM.500	Z8 23041	1	○	
	PACK OF 10 RUBBERS 400 20086	Z8 20295	1	○	